

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other Instructions on  
reverse side)

Oil Cons. *49*  
N.M. Div. Dist. 2  
Budget Bureau No. 1004-0135  
1301 W. Grand Avenue  
Artesia, NM 88210

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT - " for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME Lea "D"	
2. NAME OF OPERATOR The Wiser Oil Company		8. WELL NAME AND NO. 23	
3. ADDRESS OF OPERATOR P.O. Box 2568 Hobbs, New Mexico 88241		9. API WELL NO. 30-015-29703	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface  1330' FNL & 1330' FWL Unit F		10. FIELD AND POOL, OR WILDCAT Grayburg Jackson Seven Rivers	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 26-T17S-R31E	
14. PERMIT NO	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3839'	12. COUNTY OR PARISH Eddy County	13. STATE NM

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <u>Re-perf. &amp; acidize</u>	
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

5/02/00 MIRU Key Well Service. POH w/rods. Bottom rod unscrewed. RIH w/fishing tool. Could not get fish. POH w/rods. ND WH. NU BOP's. POH w/2-7/8" tbg.

5/03/00 RIH w/4-3/4" bit & scraper on 2-7/8" EUE tbg. Tag @ 3980'. POH w/bit & scraper. RU Computalog WL & perforate San Andres Grayburg & Upper Jackson f/3449'-52', 71', 3508', 09', 94'-97', 3654'-56', 79', 80', 85', 3861'-74', 78'-3900', 10', 15', 20', & 24'-31' w/4 SPF (260 holes). RIH w/RBP & pkr. to 3960'. Set RBP. Pull up hole to 3800' & set pkr.

5/04/00 RU Hughes Services. Test tbg. to 4000#. Acidize Jackson perms. 3822'-3931' w/2000 gals. 15% pad acid & 3000# block in 15 stages. Good block action. MTP 800# @ 5 bpm. ATP 400# @ 5 bpm. ISIP well on vac. Release pkr. Moved RBP to 3793'. Set pkr. @ 3397'. Acidized Grayburg Vacuum perms. w/4000 gals. 15% pad acid & 4000# salt in 15 stages. Good block action. MTP 350# @ 5 bpm. ATP 100# @ 5 bpm. ISIP 0#. RIH & latch onto RBP. POH. RIH w/2-7/8" tbg. Tag @ 3805'. Tried to wash down. POH w/tbg. LD PS. RIH w/notched collar, SN & 2-7/8" tbg.

5/05/00 RIH w/tbg. Tag @ 3920'. Washed down to 3985'. Pumped 110 bbls. fresh water. Pull up 60'. Did not tag. ND BOP's. NU WH. RIH w/rods & 1-3/4" x 16" RHAC pump. Left well pumping to Battery. RDMO.

ACCEPTED FOR RECORD

NOV 5 2001

18. I hereby certify that the foregoing is true and correct.

SIGNED Mary Jo Turner

TITLE Production Tech II

ALEXIS C. SWOBODA  
PETROLEUM ENGINEER

August 18, 2001

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instruction On Reverse Side