

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons Division

311 Sublet IN TRIPLICATE *

(Other Instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

clsf

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT - " for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.
LC-029418-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. ☒ OIL ☐ GAS ☐ OTHER

7. UNIT AGREEMENT NAME
Lea "D"

2. NAME OF OPERATOR
The Wiser Oil Company

8. API WELL NO.
30-015-29705

3. ADDRESS OF OPERATOR
P.O. Box 2568 Hobbs, New Mexico 88241

9. WELL NO.
11

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

10. FIELD AND POOL, OR WILDCAT
Grayburg Jackson 7-Rivers

2595' FNL & 1339' FEL
Sec. 26-T17S-R31E
Unit G

RECEIVED
OCD ARTESIA

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 26-T17S-R31E

14. PERMIT NO

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3761'

12. COUNTY OR PARISH
Eddy

13. STATE
NM

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☒

(Other) Perforate, Acidize & Frac

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

08/28/97 NU WH & BOP. RIH w/4-3/4" bit, 6 3-1/8" drill collars & 2-7/8" tbg. to 4036'.

08/29/97 Drilled cmt. f/4036'-4083'. HES perforated San Andres Upper Jackson f/3979'-89', 98', 4002', 03' & 09'-14' w/1 SPF (20 holes). RIH w/Baker pkr on 2-7/8" tbg. Spotted acid @ 4010'. Set pkr. @ 3869'. HES broke down & acidized perms. 3979'-4014' w/3000 gals. 15% NE-FE acid & 40 ball sealers. Formation broke @ 4356#. ATP 3054# @ 6.1 bpm. MTP 3907# @ 6.3 bpm. Balled out w/4500#. ISIP 2303#. 5 min. 2289#. 10 min. 2267# 15 min. 2248#.

09/02/97 HES perforated San Andres Vacuum f/3839', 40', 41', 56'-59', 3908', 09', 10', 12', 28', 29', 38', 39', & 40' w/1 SPF (16 holes). RIH w/Baker RBP & pkr. on 2-7/8" tbg. Set RBP @ 3966'. HES spotted acid & set pkr. @ 3740'. Broke down & acidized perms. 3839'-3940' w/2400 gals. 15% NE-FE acid & 32 ball sealers. Formation broke @ 3193#. ATP 3000# @ 4.2 bpm. MTP 3141# @ 4.6 bpm. Balled out w/4750#. ISIP 2062#. 5 min. 1853#. 10 min. 1817#. 15 min. 1790#.

09/03/97 RIH w/RBP, pkr., & tbg. Set RBP @ 3966'. POH & LD tbg. & pkr. ND BOP. Removed WH. Installed frac valve.

09/04/97 HES frac'd. San Andres Vacuum perms. 3839'-3940' w/3000 gals. gelled water, 16,100 gals. 20# Delta frac & 40,400# 16/30 Brady sand. ATP 3800# @ 31 bpm. Screened out w/13,000# sand in perms. MTP 5200#. ISIP 4175#. 5 min. 3713#. 15 min. 3477#.

09/08/97 NU BOP. RIH w/2-7/8" notched collar on 2-7/8" tbg. Tagged sand @ 936'. Cleaned out sand f/936'-1311', fell thru. RIH to 2936'. Cleaned out sand f/2936'-3000'.

18. I hereby certify that the foregoing is true and correct.

SIGNED Mary Jo Turner TITLE Completion Department DATE January 7, 1998

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

