

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.

30-015-30159

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER ☐

2. Name of Operator

Marathon Oil Company

3. Address of Operator

P.O. Box 2409 Hobbs, NM 88240

4. Well Location

Unit Letter C : 660 Feet From The North Line and 1980 Feet From The West Line

Section 34 Township 18-S Range 28-E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

GL 3536' KB 3542'

7. Lease Name or Unit Agreement Name

Samuel Burns 34 State

8. Well No.

1

9. Pool name or Wildcat

Travis: Upper Penn

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: New Well Completion ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/5/98 MIRU PU. NU BOP. RIH w/bit & DC's. DO cmt to 11,039' BPTD. Circ hole clean. POOH w/bit & DC's. Run logs. RIH w/pkr, set at 3000'. Perf 9270' 1 ft w/4 SPF. Rel pkr, POOH. RIH w/cmt ret at 9160'. Pump 160 sxs cmt. POOH w/retainer. RIH, DO cmt, POOH. Perf 8240' 1 ft w/4 SPF. RIH w/cmt ret at 8190'. Pump 765 sxs cmt. POOH w/retainer. RIH, DO cmt, POOH. Circ hole clean.  
5/14 Perf 9742-80', 9790-98' w/4 SPF, 90 deg phasing, 184 hole. RIH w/pkr & 2 7/8 prod tbg. ND BOP. Set pkr at 9620'. Test pkr, OK. Swab well.  
5/20 Attempt to acidize perms w/14,000 gals 15% acid. Communicated after pumping 1558 gals acid. Found leak, repaired it. Swab well.  
5/21 Shut well in. Set blanking plug in profile nipple at 9653'. Rel on/off tool & circ pkr fluid. Test tbg annulus, slight leak. Test tbg. NU BOP. TOH w/ on/off tool.  
5/22 TIH w/ on/off tool on 2 7/8" tbg. Test tbg. ND BOPE. NU tree assy. Load & test annulus. Test tbg. Retrieve blanking plug. Made 1 swab run. RDPV.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Kelly Cook

TITLE Records Processor

DATE 5/29/98

TYPE OR PRINT NAME Kelly Cook

TELEPHONE NO. 393-7106

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM  
DISTRICT II SUPERVISOR

APPROVED BY

TITLE

DATE

6-1-98

CONDITIONS OF APPROVAL, IF ANY: