

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. <b>30-015-30225</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>David Crockett 27 State</b>
8. Well No. <b>2</b>
9. Pool name or Wildcat <b>Travis; Upper Penn</b>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>GL 3574 KB 3592</b>

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator <b>Marathon Oil Company</b>	
3. Address of Operator <b>P.O. Box 2490 Hobbs, NM 88240</b>	
4. Well Location Unit Letter <b>F</b> : <b>1980</b> Feet From The <b>North</b> Line and <b>1830</b> Feet From The <b>West</b> Line Section <b>27</b> Township <b>18-S</b> Range <b>28-E</b> NMPM <b>Eddy</b> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>GL 3574 KB 3592</b>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **New Well Completion** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/23/98 MIRU PU. NU BOPE. RIH w/bit. DO to 9467'. Pickle tbg w/750 gals 15% acid.  
6/24 DO to 9500'. Circ clean. Perf 9152-9158'. 2 SPF, 12 holes. RIH w/pkr, set at 9091'. Swab. Break down perfs w/2% KCL water. Swab.  
6/27 Rel pkr, POOH. RIH w/cmt retainer, set at 9090'. Cement squeeze perfs 9152-9158' w/75 sxs cement. TOOH w/tools. RIH w/bit. DO to 9170'. Circ clean. Test sqzd perfs to 300 psi, OK. RIH w/bit. DO to 9610'. Circ clean.  
7/2 RIH w/6 1/8" core tools. Core from 9610-9790'. POOH w/tools. RIH w/bit & dc's to 9567'.  
7/7 Drill open hole from 9790-9856'. Circ clean. TOH w/tools. Log well from 9750-9856'. Tools got stuck.  
7/10 Recovered tools. Log well 9564-9840'. RIH w/pkr on 2 7/8" prod tbg.  
7/11 ND BOP. Land tbg at 9584'. Set pkr at 9518'. Swab well.  
7/14 RU CT unit. Test BOPE. Acidize open hole 9655-9760' w/2000 gals 15% acid. RD CT unit. Swab well.  
7/22 RD PU.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 8/3/98  
TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

**ORIGINAL SIGNED BY TIM W. GUM  
DISTRICT II SUPERVISOR**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE 8-5-98

CONDITIONS OF APPROVAL, IF ANY: