

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**DISTRICT I**

P.O. Box 1980, Hobbs NM 88241-1980

**DISTRICT II**

P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. <b>30-015-30315</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>Samuel Burns 34 State</b>
8. Well No. <b>2</b>
9. Pool name or Wildcat <b>Travis; Wolfcamp</b>

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator <input checked="" type="checkbox"/> <b>Marathon Oil Company</b>	
3. Address of Operator <b>P.O. Box 2490 Hobbs, NM 88240</b>	
4. Well Location Unit Letter <b>E</b> : <b>1876</b> Feet From The <b>North</b> Line and <b>490</b> Feet From The <b>West</b> Line Section <b>34</b> Township <b>18-S</b> Range <b>28-E</b> NMPM <b>Eddy</b> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>GL 3531' KB 3542'</b>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐


**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **Place well on Rod Pump** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/5/98 MIRU pulling unit. ND wellhead. NU BOPE. Rel on/off tool. Rel pkr, POOH. RIH w/2 7/8" production tubing. ND BOP. Set TAC. NU wellhead. RIH w/pump and rods. Load and test, OK.  
11/7/98 RD pulling unit.

TAC at 8615'.  
SN. at 8964'.  
End of tbg 8996'.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Kelly Cook*

TITLE

Records Processor

DATE

1/27/99

TYPE OR PRINT NAME

Kelly Cook

TELEPHONE NO.

393-7106

(This space for State Use)

**ORIGINAL SIGNED BY TIM W. GUM**  
**DISTRICT II SUPERVISOR**

APPROVED BY

*BGA*

TITLE

DATE

4-15-99

CONDITIONS OF APPROVAL, IF ANY: