

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.	30-015-30395
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Samuel Burns 34 State
8. Well No.	3
9. Pool name or Wildcat	Travis; Upper Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GL 3535' KB 3553'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Marathon Oil Company
3. Address of Operator P.O. Box 2490 Hobbs, NM 88240	4. Well Location Unit Letter B : 450 Feet From The North Line and 2100 Feet From The East Line
5. Section 34 Township 18S Range 28E NMPM Eddy County	6. 10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3535' KB 3553'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: New Well Completion ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/2 MIRU pulling unit. NU BOPE. RIH w/dc's, tag cmt at 8533'. DO DV tool at 8543'. DO to 9954'. Circ clean. Pickle tbg w/1500 gals 15% HCL. PUH to 9908', spot 1000 gals 15% acid. TOOH. Run logs 8990-9990'.
2/5 Perf 9842-54', 9860-70', 9888-96', 9904-08', 4 SPF 120 deg phasing, 136 holes. TIH w/pkr, set at 9744'. ND BOP. NU wellhead. Swab
2/10 Acid frac 9842-9908' w/4250 gal pad & 8500 gals 15% acid w/204 BS. Swab back acid. Flow test well.
2/13 RD pulling unit.
2/20 Place well on rod pump. RIH, rel pkr at 9744'. POOH. POOH w/tbg. RIH w/2 7/8" tbg. RIH w/pump & rods. Load and test, OK.
2/23 RD pulling unit.
SN at 9942'.
End of tbg 9973'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 3/1/99
TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

APPROVED BY Jim W. [Signature] TITLE District Supervisor DATE 3-11-99
CONDITIONS OF APPROVAL, IF ANY: