SUNDR Do not use th abandoned we	UNITED STATES DEPARTMENT OF THE IN BUREAU OF LAND MANAG Y NOTICES AND REPOR is form for proposals to di bil. Use Form 3160-3 (APD)	TERIOR EMENT TS ON WELLS rill or to re-enter for such proposi	Artesia, NM an bis.	CIST FORM APPROVED OMB No 1004-0135 Expires July 31, 1996 CIST CIST OMB No 1004-0135 Expires July 31, 1996 CIST OMB No 1004-0135 Expires July 31, 1996 CIST CIST OMB No 1004-0135 Expires July 31, 1996 CIST CIST OMB No 1004-0135 Expires July 31, 1996 CIST CI
1. Type of Well Oil Well Gas Well Other				
2. Name of Operator			8. Well Name and No. Of Y Bobcat Federal #1	
OXY USA INC. 3a. Address P.O. BOX 50250 3b. Phone No. (include area cod			<u>16696</u>	9. API Well No. 30-015-30573
MIDLAND, TX 79710-0250 915-685-5717				10. Field and Pool, or Exploratory Area
4. Location of Well (Foolage, Sec., T., R., M., or Survey Description) 990 FSL 1650 FWL SESW (N) Sec 19 TIBS R29E				Turkey Track Morrow Worth 11. County or Parish, State EDDY NM
12. CHECK AP	PROPRIATE BOX(ES) TO	INDICATE NATI	JRE OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION				
Nouce of Intent	Acidize	Deepen Fracture Treat	Production (Start	·····,
Subsequent Report	Casing Repair	New Construction	Reclamation Recomplete	Well Integrity
Final Abandonment Notice	Change Plans	Plug and Abandon Plug Back	Temporarily AbWater Disposal	andon <u>Casing Cement</u>
Attach the Bond under which the following completion of the inv	he work will be performed or provi olved operations. If the operation r nal Abandonment Notices shall be	de the Bond No. on fi esults in a multiple co filed only after all red	le with BLM/BIA. Requi mpletion or recompletion purements, including recla	se vertical depths of all pertinent markers and zones. red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has TED FOR RECORD Y 0 3 1889
14. I hereby certify that the foregon Name (Printed/Typed)	ng is true and correct 02.81.2	191919171 Title		
DAVI	ID STEWART		REGULATO	RY ANALYST
Signature Vier	the second	Date	4/26/	29
		OR FEDERAL OR	STATE OFFICE USE	
Approved by			Title	Date
certify that the applicant holds leg which would entitle the applicant to		in the subject lease		r agency of the United States any faise, fictutious or

=

ATTACHMENT 3160-5 OXY USA INC. OXY BOBCAT FEDERAL #1 SEC 19 T18S R29E EDDY COUNTY, NM

•

NOTIFIED BLM 4/14/99 OF SPUD. MIRU PETERSON #308, SPUD WELL @ 0400hrs MDT 4/15/99. DRILL 17-1/2" HOLE TO TD @ 400', 4/15/99, PUMP SWEEP. RIH W/ 13-3/8" 48# H40 CSG & SET @ 400'. M&P 160sx 65:35 C/POZ W/ 6% BENTONITE + .005#/sx STATIC FREE + 2% CaCl₂ + .25#/sx CELLOFLAKE + .005 FP-6L FOLLOWED BY 200sx CL C W/ .005#/sx STATIC FREE + .005gps FP-6L + 2% CaCl₂, DISP W/ FW, PLUG DOWN @ 1400hrs MDT 4/15/99, CIRC 115sx CMT TO PIT. JIM AMOS W/ BLM NOTIFIED, BUT DID NOT WITNESS. CUT OFF CASING, WELD ON STARTING HEAD, TEST SEALS TO 500#, OK. NU BOP & CHOKE MANIFOLD, TEST BLIND RAMS, PIPE RAMS, & HYDRIL TO 500#, OK. RIH & TAG, DRILL OUT & DRILL AHEAD. WOC BEFORE DRILLING OUT 16½hrs.

DRILL 11" HOLE TO 2900' & RUN FLUID CALIPER, CONTINUE DRILLING TO TD @ 3000', 4/19/99, POOH. RIH W/ 8-5/8" 24-32# K55 CSG & SET @ 3000'. M&P 890sx 65:35 C/POZ W/ 6% BENTONITE + 1% CaCl₂ + 4#/sx GILSONITE FOLLOWED BY 200sx CL C W/ 1% CaCl₂ DISP /FW, PLUG DOWN @ 0100hrs MDT 4/20/99, CIRCULATE 150sx CMT TO PIT. BLM NOTIFIED BUT DID NOT WITNESS. ND BOP, SET SLIPS & CUT CSG. NU BOP & CHOKE MANIFOLD, TEST BLIND RAMS, PIPE RAMS, CHOKE LINES, CHOKE MANIFOLD AND SAFETY VALVES TO 5000#, OK. TEST HYDRIL TO 3000#, OK. TEST KILL LINE, MUD LINES, & CASING TO 2000#, BLM NOTIFIED OF BOP TEST, DID NOT WITNESS. RIH & TAG, DO CMT, TEST TO 500#, OK, DRILL AHEAD. WOC BEFORE DILLING OUT 15%hrs.

WA TTEMSON DENED