## State of New Mexico Ene. Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

OIL CONSERVATION DIVISION DISTRICT I P.O. Box 1980, Hobbs, NM 88240 WELL API NO 2040 Pacheco St. 30-015-31122 Santa Fe. NM 87505 DISTRICT II sIndicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 FEE X STATE DISTRICT III 6State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMITE CETYPE" (FORM C-101) FOR SLICH PROPOSALS.) Lease Name or Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS.) Rio Pecos 19 Type of Well: GAS OTHER P&A'd «Well No. 2Name of Operator Nearburg Producing Company Pool name or Wildcat 3Address of Operator Red Lake Penn 3300 N A St., Bldg 2, Suite 120, Midland, TX 79705 ₄Well Location 1980 North 660 West Feet From The Line and Feet From The Line Unit Letter 19 27E NMPM Eddy County Section Township Range DElevation (Show whether DF, RKB, RT, GR, etc.) 3585' GR 11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PERFORM REMEDIAL WORK PLUG AND ANBANDONMENT X COMMENCE DRILLING OPNS **TEMPORARILY ABANDON** CHANGE PLANS CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER: OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103 Drilled to 9.520' on 06/30/00. P&A well, approved by Tim Gum of OCD in Artesia, NM. Alerted Mike Stubblefiled of OCD. RU BJ and pump plug #1 - 9,520' 9,420' (100' - 30 sx "H" neat) LDDP to 9,160'. Plug #2 - 9,160' - 9,060' (100' - 30 sx "H" neat) LDDP to 7,150'. Plug #3 - 7,150' - 7,050' (100' - 30 sx "H" neat) LDDP to 6,104'. Plug #4 - 6,104' - 6,004' (100' - 26 sx "C" neat) LDDP to 2,930'. Plug #5 - 2,980' - 2,880' (100' - 26 sx "C" neat) LDDP to 1,555. (50' nelow 8-5/8" csg). Plug #6 - 1,555' - 1,400' (150' - 40 sx "C" + 3% CACL2) Wait 3 hrs, TIH and tag @ 1,400'. 2.) 3.) LDĎP & DC's to 50' and set surface plug. ND BOPE's and cut off wellhead. Set P&A marker. Clean location. 10.) Release rig @ 1000 hrs on 07/03/00. FINAL REPORT. I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE Regulatory Analyst DATE 07-17-00 SIGNATURE TELEPHONE NO. 915/686-8235 TYPE OR PRINT NAME Kim Stewart

(This space for State Use)

APPROVED BY