




- Wind Direction Indicators (wind sock or streamers)
- △ H₂S Monitors (alarms at bell nipple and shale shaker)
- Briefing Areas
- Remote BOP Closing Unit
- Sign and Condition Flags

EXHIBIT "D"
RIG LAYOUT PLAT

POGO PRODUCING COMPANY
SHUGART "6" FEDERAL # 1
UNIT "H" SECTION 6
T18S-R31E EDDY CO. NM