-	_ State of New		- 0155	Form C-100
Submit 3 Copics to Appropriate District Office		al Resources Department	CION	Revised 1-1 AV
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 30 015-31337	
DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease ST	ATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		6. State Oil & Gas Lease N 26639	o.	
CUNDRY NOT	TICES AND REPORTS ON			
TODA FOR TODA FOR DE	MONGALS TO DHILL OH TO DE	EPEN ON FLOOR BROWN	7. Lease Name or Unit Ag	
	RVOIR. USE "APPLICATION FO 2-101) FOR SUCH PROPOSALS.		ILLINOIS CAMP 1	8 STATE
1. Type of Well:				
OIL GAS WELL X	OTHER	- / F. C.	8. Well No.	
2. Name of Operator		RECLIVED_	1	
V-F PETROLEUM INC. 3. Address of Operator		OCD ARTESIA	9. Pool name or Wildcat	IS CAMP; MORROW NORTH
P O BOX 1889 MIDLAN	ID, TX 79702	/2		
4. Well Location P 99	SOUTH	Line and	Feet From The	EAST Line
Unit Letter:	Feet From the	28E	EDDY	County
Section 18	en 11.	Range thether DF, RKB, RT, GR, etc.)	NMPM ///	
	//////			
Check	Appropriate Box to Indi	cate Nature of Notice, I	Report, or Other Data	DT OF.
NOTICE OF IN	ITENTION TO:	SUI	BSEQUENT REFO	m
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTER	NING CASING
	CHANGE PLANS	COMMENCE DRILLIN	IG OPNS. 🔲 PLUG	AND ABANDONMENT
TEMPORARILY ABANDON	CASING TEST AND CEMENT JOB X			
PULL OR ALTER CASING			·	
OTHER:		OTHER:		
12. Describe Proposed or Completed Opwork) SEE RULE 1103. SEE REVERSE	erations (Clearly state all periore a			
I hereby certify that the information above it SKINATURE S.K. LA TYPE OR PRINT NAME (This space for State Use)	AWLIS		1	4/4/01 ELEPHONE NO. 915/683-3344 APR 0 5 2011
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	einal signed by tim w Trict H supervisor	mu		ATE
WINDING OF THE THE THE		* **		

WOC 30 hr

02/15/01

Nipple up on 9 5/8" casing & install BOP. Yellow jacket test BOP to 5,000# psi.

Drill 8 3/4" hole to 10,602'. Run openhole logs by Schlumberger.

03/25/01

Ran 10,613' 5 ½" 17# L-80 LT&C casing set @ 10,602'. Cement with 820 sx premium light weight + 200 sx class "H" cement. Pump plug down with fresh water. Bump plug & pressure test casing to 3,100# psi. Bleed back & check float for flowback set slips & cut off casing. Ran temperature survey. Found TOC @ 6,950'. Release rig. Prepare for completion.