Submit 3 Copies to Appropriate

**TEMPORARILY ABANDON** 

**PULL OR ALTER CASING** 

work) SEE RULE 1103.

State of New Mexico Energy, Minerals and Natural Resources Department



Form C-103 Revised 1-1-89

District Office OIL CONSERVATION DIVISION DISTRICT I WELL API NO. 2040 Pacheco St. P.O. Box 1980, Hobbs NM 88241-1980 30-015-31930 Santa Fe, NM 87505 DISTRICT II 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 STATE X FEE DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.) OXY WOOF STATE 1. Type of Well: OIL U GAS WELL X OTHER 8. Well No. 2. Name of Operator OXY USA WIP Limited Partnership 192463 9. Pool name or Wildcat 3. Address of Operator P.O. Box 50250 Midland, TX UNDS RICHARD KNOB ATOKA MORROW 4. Well Location Feet From The. Unit Letter \_ Feet From The Line and . Line **18**S **NMPM** County Township Range 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: **NOTICE OF INTENTION TO:** ALTERING CASING PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK

OTHER: OTHER: \_ 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOB X

SEE OTHER SIDE

**CHANGE PLANS** 



PLUG AND ABANDONMENT

	RECEIVED OCD - ARTESIA
	OCD ARTESIA
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE	DATE SINOI
TYPE OR PRINT NAME David Stewart	TELEPHONE NO. 915-685-5717
(This space for State Use)  ORIGINAL SIGNED BY TIM W. GUM DISTRICT II SUPERVISOR TITLE	AIG 2 6 2011
CONDITIONS OF APPROVAL, IF ANY:	

ATTACHMENT C-103 OXY USA WTP LP OXY WOOF STATE #1 SEC 2 T18S R24E EDDY COUNTY, NM

NOTIFIED NMOCD 8/9/01 OF SPUD. MIRU UTI 503, SPUD WELL @ 0030hrs MDT 8/10/01. DRILL 17-1/2" HOLE TO TD @ 410', 8/10/01, PUMP SWEEP. RIH W/ 13-3/8" 48# H40 CSG, SET @ 408'. M&P 300sx Cl H W/ 10% A10B + .25#/sx CELLOFLAKES + 10#/sx LCM-1 + 1% CaCl<sub>2</sub> FOLLOWED BY 200sx CL C W/ 2% CaCl<sub>2</sub>, DISP W/ FW, PLUG DOWN 8/10/01, CIRC 100sx CMT TO PIT, POOH, WOC-6hr. NMOCD NOTIFIED, DID NOT WITNESS. CUT OFF CASING, WELD ON WELL HEAD, TEST TO 1000#, OK. NU BOP & TEST BOP & CASING TO 500#, OK. TEST PIPE RAMS & HYDRIL TO 500#, OK. TOTAL WOC-18hrs, RIH & TAG, DRILL OUT & DRILL AHEAD 8/11/01.

DRILL 11" HOLE TO TD @ 1450', 8/12/01, CHC. RIH W/ 8-5/8" 32# K55 CSG & SET @ 1448'. M&P 600sx Cl C W/ 2% CaCl<sub>2</sub> + .25#/sx CELLOFLAKES + 5#/sx GILSONITE FOLLOWED BY 200sx Cl C CMT W/ 2% CaCl<sub>2</sub>, DISP W/ FW, PLUG DOWN 8/12/01. CIRC 150sx CMT TO SURFACE, WOC-4hrs, NOTIFIED NMOCD DID NOT WITNESS. CUT OFF CSG & INSTALL B SEC, TEST TO 1500#, OK. NU BOP & CHOKE MANIFOLD, TEST BLIND RAMS, PIPE RAMS, CHOKE LINES, CHOKE MANIFOLD AND SAFETY VALVES TO 5000#, OK. TEST HYDRIL, MUD LINES AND CSG TO 2500#, OK. RIH, DO CMT & SHOE, DRILL NEW FORMATION, TEST CSG, OK. DRILL AHEAD 8/13/01.

gray & section to the section of