

11/28/2001 CMIC:gary henrich
sip 50#, bleed well down, ru baker atlas wl, rih w/cibp & set @ 6640', pooh, rih
w/cement bailer & dump 3 sx cement on top of cibp making pbtd 6610', pooh, sisd!

11/29/2001 CMIC:gary henrich
si due to bad weatherford

11/30/2001 CMIC:gary henrich
load csg. w/30 bw, ru baker atlas wl, rih w/4" tag guns loaded w/predator
charges @ 2 spf, perforate cisco A formation from 6456'- 6464', 6390'-
6396', 6312'-6316', 6272'- 6275' (46 holes), pooh, rd wl, rih w/retriev-a-matic
pkr., s.n. & 195 jts. 2 7/8" tbg., set pkr. @ 6194', test csg. to 1500#(OK),
nd bop, nu tree, sisd!

12/01/2001 CMIC:gary henrich
sitp 0#, ru swab, rec. 34 bw in 10 hrs., ifl surface, ffl dry, well swabbed
dry in 3 hrs., made 1 run per hr. rest of day, had no fluid entry, slight
gas while pulling swab, sisd!

12/02/2001 CMIC:gary henrich
sitp 0#, ru swab, no fluid entry overnight, rd swab, nu tree saver, ru bj
services, acidize well w/4000 gals. 15% hcl w/additives & n2 as follows, pump 3
bbls. acid, 20,000 scf n2, 93 bbls. acid comingled w/1000 scf n2 & 40 ball
sealers, dropped balls in 10 stages of 4 balls per stage, formation broke @
6749#, min. treating press. 2348#, max. 6749#, average 3800#, average rate 4.3
bpm, isdp 2446#, 5 min. 2081#, 10 min. 1739#, 15 min. 1532#, si, rd bj, nd tree
saver, sitp 1400#, open well to pit on 12/64" choke, rec. 36 bw in 7 hrs., gas hit
after 6 hrs. flowing, fftp 125# on f/o choke, had 4' to 6' flare, sisd!

12/04/2001 CMIC:gary henrich
sitp 1200#, open well to pit on 14/64" choke, rec. 12 bw in 3 hrs. & well
died, ru swab, rec. 110 bw in 7 hrs., ifl 1400', ffl 4800', 6' flare, rd
swab, sisd! (36bbls.
over load)

12/05/2001 CMIC:gary henrich
sitp 1500#, open well to pit on 15/64" choke, rec. 3 bw in 1 hr. & well
died, ru swab, rec. trace of oil & 84 bw in 7 hrs., ifl 2800', ffl 4800', had
4' flare throughout day, rd swab, sisd!

12/06/2001 CMIC:gary henrich
sitp 1400#, open well to pit & bleed well down in 1 hr., nd tree, nu bop, release
pkr. & pooh w/2 7/8" tbg. & pkr., ru baker atlas WL, rih & set cibp @6260', pooh, rih
w/bailer & dump 3 sx cement on top of cibp making pbtd 6230', pooh, rd wl, rih
w/194 jts. 2 7/8" l-80 tbg. to 6155', nd bop, nu tree, sisd!

12/07/2001 CMIC:gary henrich
rig unit down, clean loc., move off loc.

OXY WOOF STATE #1

11/15/2001 CMIC:gary henrich

sitp 1100#,open well to pit on 12/64" choke,well bled down to 0# in 1 hr.,ru swab,rec.12 bw in 9 hrs.,ifl 6900',ffl dry,well swabbed dry in 1 hr.,made 1 run per hr. rest of day,had 300' of fluid entry per hr.,3' flare,rd swab,sisd!

11/16/2001 CMIC:gary henrich

sitp 1100#,open well to pit on f/o choke,well bled down in 1 hr.,ru reverse pump & kill well w/ 45 bbls.3%kcl,nd tree,nu bop,release pkr. & pooh w/ 2 3/8"tbg. & pkr.,sisd!

11/17/2001 CMIC:gary henrich

sip 50#,ru baker atlas,rih w/cibp,set cibp @ 7640',pooh,rih w/ dump bailer,dump 3 sx cement on top of cibp,pooh,rih w/4" tag gun loaded w/predator charges @ 2spf,perforate cisco canyon from 7334'-7328',6770'-6764',6750'-6747',6684'-6672',6668'-6664',(67 holes),rd wl,rih w/baker retrievematic pkr.,2 7/8" sn,208 jts. 2 7/8" tbg.,set pkr. @ 6591',nd bop,nu tree,test csg. to 1500#(OK),sisd!

11/18/2001 CMIC:gary henrich

sitp 0#,sicp 0#,ru swab,rec. 36 bw in 5 hrs.,ifl surface,ffl dry,well swabbed dry in 4 hrs.,wait 1 hr. & make swab run,no fluid entry,slight gas while pulling swab,rd swab,sisd!

11/20/2001 CMIC:gary henrich

sityp 0#,ru swab,rec. 9 bw in 9 hrs.,ifl 5100',ffl dry,well swabbed dry in 1 hr.,make 1 run per hr. rest of day,had no fluid entry,slight gas while pulling swab,sisd!

11/21/2001 CMIC:gary henrich

sip 0#,nu tree saver,ru bj services,acidize well w/ 4000 gals. 15%hcl acid w/additives & 1000 scf n2 per bbl. & 60 ball sealers as follows,pump 3 bbls. acid,20,000 scf n2,91 bbls.acid comingled w/ 1000 scf n2 per bbl. dropping balls in 6 stages of 10 balls per stage,flush to top perf. w/ comingled 3% kcl,formation broke @4156#,min. treating press. 1499#,average rate 6 bpm,max. 4156#,average 3800#,isdp 2092#,5 min. 2034#,10 min.2015#,15 min.2015#,si rd bj,nd tree saver,open well to pit on 10/64"choke,sitp 1900#,rec. 30 bw in 5.5 hrs.,fftp 120# on f/o choke w/ 6' flare,gas hit after flowing back 5 hrs.,sisd!

11/22/2001 CMIC:gary henrich

sitp 1500#,open well to pit on 12/64" choke,well bled down in 1 hr.,no fluid rec.,ru swab,rec. 3 bo,145 bw in 9 hrs.,ifl 1500',ffl 5800',had 5' to 6' flare,rd swab,sisd!

11/24/2001 CMIC:gary henrich

sitp 900#,open well to pit on 14/64" choke,well bled down to 0# in 1 hr.,rec. 0 bf,ru swab,rec. 5 bo,121 bw in 8 hrs.,ifl 1500',ffl 5800',had 2' flare,rd swab,sisd!

11/27/2001 CMIC:gary henrich

sitp 400#,bleed well down to pit in 30 min.,load tbg. w/24 bbls. 3% kcl,nd tree,nu bop,release pkr.,pooh w/tbg.,sn & pkr.,sisd!