Form 3160-5 (August 1999)

## ED STATES

TOF THE INTERIOR DEPARTM

FORM APPROVED OMB NO. 1004-0135 Oil Line

Expires: November 30, 200	ONL	110.	1001	01.	,,,
	Expires:	Nove	mber	30,	2000

(August 1999)	DEPARTML	OF THE INTERIOR	U	l Cons.	Expires: Nove	ember 30, :	2000	
		ND MANAGEMENT	N.M.	DIV-Dist.	2. Lease Serial No.			
	<u> </u>	AND REPORTS ON WI	1004 141	Crand As	NOACOL NAI			
	SUNDRY NOTICES A	AND REPORTS ON WI	ELERSO I VV.	Sianu A	21.0 Indian, Allottee	or Tribe Na	ine	
	Do not use this form for	proposas to drill or to re-enter	an Artesia	, NM 88	210			
	abandoned well. Use Forr	m 3100-3 (APD) for such propo	osais.					
					7. If Unit or CA/Agreement, Name and/or No.			
SUBMIT IN TRIPLICATE - Other instructions on reverse side								
	SUBMIT IN TRIPLICATE -	CO TOTAL	<del>- }</del>		4			
. Type of Well		ARTESIA	<b>A</b> Ò		8. Well Name and N			
X Oil Well	ON WALL Gas Well Other 9				Shugart West 24			
_=		384EZI - 1808	Federal "A" #4					
. Name of Operator	c Inc	3851-18	9. API Well No.					
KCS Resource	5, 111c.	3h I	Phone No. (include a	rea code)	]			
la. Address	. Ct. 040 Tules 0		188-8283	,	10. Field and Pool,	or Explorate	гу Агеа	
7130 South L	<u>ewis, Ste. 840 Tulsa, O</u>		100 0200		Shugart	•		
1. Location of Well (	Footage, Sec., T., R., M., or Surve	y Description)			3			
Sec24-T18S-R					11. County or Paris	h, State		
990'FNL & 99	0'FEL of Sec.24				i		NM	
					Eddy		MCI	
	12. CHECK APPROPRI	ATE BOX(ES) TO INDICA	TE NATURE OF NO	OTICE, REPORT	OR OTHER DATA			
	- CHECK ATTIOTION							
TYPE	OF SUBMISSION		TY	PE OF ACTION				
			¬¬¬	Productio	on (Start/Resume)	Water Shu	ıt-Off	
No	tice of Intent	Acidize	Deepen			*** ** * .	•	
		Alter Casing	Fracture Treat	Reclamat	ion $\square$	Well Integ	rity	
X Su	bsequent Report	Casing Repair	New Construction	Recomple	ete	Other		
ننا	•		_	Tampora	rily Abandon			
☐ Fir	nal Abandonment Notice	Change Plans	Plug and Abandon	rempora.				
```		Convert to Injection	Plug Back	Water Di	.sposal			
	sed or Coommpleted Operation (clear					imata du	ration thereof	
following complesting has bee determined that 3/09/02 - 3/10/02 - Premium W. to pit. W 3/11/02 - 3/16/02 - Mod.Halli Circulate 3/17/02 - Fill back 3/31/02 - 4/01/02 - FWCA .6%	is to deepen directionally or recomped under which the work will be perletion of the involved operations. If n completed. Final Abandonment Note final site is ready for final inspection.  MIRU Patterson #55. Spin Drill 17-1/2" hole to /2%cc. 1/4pps Flocele @ itness: Homer Scienz.  Weld on head. Test to Drill 11" hole to 2814 burton light premium 2% 69sks to pit. Witness: Weld on 8-5/8" head. N side with 11 yds of Read Drill 7-7/8" hole to 6 Ran 5-1/2" 17 & 15.5# Halad-322, 250sks 50/50 mm. 50/50 Poz. @ 14.15 proceed to 12 and 15 proceed to 15 15 procee	dictices shall be filed only after and 10:00pm.  767'. Ran 21 jts 13- 12 ppg. Tail 200sks  300 psi. NU BOPE & 1 '. Ran 67jts 8-5/8" cc. 1/2 pps floceld James A. Amos. U BOPE. Test 250/30d dimix. 364'. Ran logs. J55 w/stage tool @ 1 Poz1% FWCA. Oppog - Close tool and	all requirements, in 3/8" K55 72# Fremium plus test to 1000 p 32# J55 csg te. Tail 200 sk 00 psi - Annul 4293'. Cmnt 1 test to 2600	csg. Cmt www. w/2% cc @ esi. Test cs. co 2814'. Cmt. stalliburt. ar. 250/15. Lst stage 30. Cmt w/385. psi.	2.370sks Hallib 14.8 ppg. Circ 15 to 800 psi. 15 w/550 sks le 16 con Premium Plu 16 00 psi. Test 16 0sks scavenger 16 0sks Interfill	urton lulate 1 ead. us 2%cc. csg to 50/50 r	ight 10 sks 1500psi.	
4/06/02 -	Drill out stage tool a	and test csg to 3000	psi. CBL rai	n 8344° <u>-692</u> 0	1 TUC CBL rail			
4350'-180	M' <del>'et CIBL 8320, (1'0</del> 1	<del>D) = = = = </del>		econd Page	attached)	7-7		
14 I hereby certify t	hat the foregoing is true and correct		Title	k a				
Name (Printed/T) Kaye /	ypea) Allav		Produ	uction Tech	nician			
Kaye /	2116,	•		1 1				
~ ~		De	Date 4/29/0		<b>8 PABYAK</b> -	===		
	TI	IS SPACE FOR FEDER	AL OR STATE O	FFICE USE	OL MOINE	сK		
		<del></del>	Title		Date			
Approved by		`						
	wal, if any, are attached. Approval		nt or Office lease					
which would entitle t	he applicant to conduct operations there	~n.			L. A. a. u. donorum	ant or agen	cy of the Unite	

SOUSHAY - 1 AM 9: 40

HECENED