
## **Mack Energy Corporation**

Exhibit #11 MIMIMUM CHOKE MANIFOLD 3,000, 5,000, and 10,000 PSI Working Pressure 2 M will be used or greater 3 MWP - 5 MWP - 10 MWP



Mud Pit

Reserve Pit

\* Location of separator optional

**Below Substructure** 

		Mimimum 3,000 MWP				requirements 5,000 MWP			10,000 MWP		
			NOMINAL	Rating	I.D.	Nominal	Rating	I.D.	Nominal	Rating	
No.		I.D.	3"	3,000	1.D.	3"	5.000		3"	10,000	
1	Line from drilling Spool		3"	3.000		+	5.000				
2	Cross 3" x 3" x 3" x 2"			3,000		<del> </del>	3,000			10,000	
2	Cross 3" x 3" x 3" x 2"				-	<del> </del>				10.000	
3	Valve Gate Plug	3 1./8		3,000	3 1/8		5,000	3 1/8		10,000	
4	Valve Gate	1 13/16		3,000	1 13/16		5,000	1 13/16		10,000	
	Plug	2 1/16		3,000	2 1/16		5,000	2 1/16		10.000	
4a	Valves (1)	2 1.10		3,000			5,000			10.000	
<u>5</u>	Pressure Gauge Valve Gate	3 1/8		3,000	3 1/8		5,000	3 1/8		10,000	
	Plug		-	3,000	2"		5,000	2"		10,000	
7	Adjustable Choke (3)	2"		3.000	1"	-	5,000	2"		10,000	
8	Adjustable Choke	1"		3,000	<del>                                     </del>	3"	5,000		3"	10,000	
9	Line		3"			2"	5,000		2"	10,000	
10	Line	ļ	2"	3,000		+		T		10.000	
11	Valve Gate Plug	3 1/8		3,000	3 1/8		5,000	3 1/8		10.000	
			3"	1,000		3"	1,000		3"	2.000	
12	Line		3"	1.000		3"	1,000		3"	2.000	
13	Line Remote reading compound			3,000			5,000			10,000	
	Standpipe pressure quage		2' x5'		+	2' x5'	<del>                                     </del>		2' x5'		
15	Gas Separator	<del> </del>	4"	1,000	<del> </del>	4"	1,000		4"	2,000	
16_	Line	<del> </del>	4"	1.000	+	<del>  '                                   </del>		1		10,000	
17	Valve Gate Plug	3 1/8		3,000	3 1/8		5,000	3 1/8		10.000	

- (1) Only one required in Class 3M
- Gate valves only shall be used for Class 10 M
- Remote operated hydraulic choke required on 5,000 psi and 10,000 psi for drilling.

## EQUIPMENT SPECIFICATIONS AND INSTALLATION INSTRUCTION

- All connections in choke manifold shall be welded, studded, flanged or Cameron clamp of comparable rating. 1.
- All flanges shall be API 6B or 6BX and ring gaskets shall be API RX or BX. Use only BX for 10 MWP. 2.
- All lines shall be securely anchored. 3.
- Chokes shall be equipped with tungsten carbide seats and needles, and replacements shall be available.
- Choke manifold pressure and standpipe pressure gauges shall be available at the choke manifold to assist in regulating chokes. As an alternate with automatic chokes, a choke manifold pressure gauge shall be located on the rig floor in conjunction with the standpipe pressure gauge.
- Line from drilling spool to choke manifold should bee as straight as possible. Lines downstream from chokes shall make turns by large bends or 90 degree bends using bull plugged tees.