

## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELL

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X		

Artesia, New Mexico

January 30, 1941

Place

Date

OIL CONSERVATION COMMISSION,

Santa Fe, New Mexico.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the

S. P. YATES

Taylor Ross

Well No. 1

in the

Company or Operator

Lease

NW 1 SW 1

of Sec. 22

T. 19S

R. 25E

N. M. P. M.,

Wildcat

Field,

Eddy

County

The dates of this work were as follows:

January 22, 1941

Notice of intention to do the work was ~~submitted~~ submitted on Form C-102 on January 20 1941 and approval of the proposed plan was (~~submitted~~) obtained. (Cross out incorrect words)

## DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Well was plugged as follows: Cement plug using 10 sacks of cement in bottom of hole; filled from top of above plug with mud to 840'; pulled 7" casing. 2nd plug from 840' using 10 sacks cement; filled with mud to 655'; 3rd plug from 655' using 15 sacks of cement; mud from top of 3rd plug to 440'; cemented 4th plug with 10 sacks of cement from 440' up. Pulled 8" casing and set plug from 251' to 248', pulled cellar and cemented 4' pipe marker with 5 sacks of cement.

Witnessed by E. G. Minton

Artesia Well Supervisor

Name

Company

Title

Subscribed and sworn to before me this 4th

I hereby swear or affirm that the information given above is true and correct.

day of February 19 41

Name

S. P. Yates

Position

Operator

Representing

S. P. YATES

Company or Operator

My Commission expires October 15, 1941

Address 215 Ward Bldg.; Artesia, N. Mex.

Remarks:

Ray Yarbrough  
Name  
OIL & GAS INSPECTOR

Title

## PROBLEM 1

Let  $f: \mathbb{R} \rightarrow \mathbb{R}$  be a function satisfying

for all  $x, y \in \mathbb{R}$ .

(a) Show that  $f(0) = 0$ .

(b) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(c) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(d) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(e) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(f) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(g) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(h) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(i) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(j) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(k) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(l) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(m) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(n) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(o) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(p) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(q)

(r)

(s)

(t)

(u)

(v)

(w)

(x)

(y)

(z)

(aa) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(ab) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(ac) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(ad) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(ae) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(af) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(ag) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(ah) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(ai) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(aj) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(ak) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(al) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(am) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(an) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(ao) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .

(ap) Show that  $f(x) = 0$  for all  $x \in \mathbb{R}$ .