

OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	<input checked="" type="checkbox"/>		

Artesia, New Mexico

April 9, 1948

Place

Date

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____
Jones & Yates **Pickrel** Well No. **1** in the _____

Company or Operator **NEISWISSE** of Sec. **5**, T. **19S**, R. **26E**, N. M. P. M.,
Artesia Field, **Eddy** County.

The dates of this work were as follows: **March 1, 1948**

Notice of intention to do the work was (was not) submitted on Form C-102 on **January 26,** 19 **48**
and approval of the proposed plan was (was not) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED
Shot off and pulled 250' of 13" OD casing which was set at 300'. Shot off and pulled 250' of 10" casing which was set at 564'. Shot off and pulled 250' of 8" casing which was set at 650'. Filled hole with mud from 1050' to 670'. Set 10 sacks cement plug at 670' then filled hole back to 250' with heavy mud. Set cement plug at 250' using 10 sacks cement. Filled hole with heavy mud to surface and set 4" regulation pipe marker at surface with 5 sacks cement.

Filed form C-105, November 14, 1947

Witnessed by _____ Name **Stanley L. Jones** Company _____ Title _____

Subscribed and sworn before me this **8**

I hereby swear or affirm that the information given above is true and correct.

day of **April**, 19 **48**Name **Stanley L. Jones**Position **Partner**Representing **JONES & YATES**

Company or Operator

Address **Box 464, Artesia, New Mexico**

My commission expires

Remarks:

Notary Public
Artesia Representative
Name _____
Title _____