

NEW MEXICO OIL CONSERVATION COMMISSION
DRAWER DD
ARTESIA, NEW MEXICO

PLUGGING
FIELD REPORT FOR CEMENTING OF WELLS

Operator <u>JONES & HAILE</u>		Lease <u>HANSON-STATE</u>		Well # <u>1</u>	
Location of Well	Unit <u>NESEW K</u>	Section <u>32</u>	Township <u>19</u>	Range <u>27</u>	County <u>EDDY</u>
PLUGGING Drilling Contractor <u>HERMIT HOOVER</u>		Type of Equipment <u>CABLE TOOL</u>			
<u>APPROVED CASING PROGRAM</u>					
Size of Hole	Size of Casing	Weight Per Foot	New or Used	Depth	Sacks Cement
<u>8"</u>	<u>7"</u>	<u>20 #</u>	<u>USED</u>	<u>350</u>	<u>CIRCULATE</u>
Casing Data:					
Surface _____ joints of _____ inch _____ # Grade _____ (Approved) (Rejected) _____					
Inspected by _____ date _____					
Cementing Program					
Size of hole _____ Size of Casing _____ Sacks cement required _____					
Type of Shoe used _____ Float collar used _____ Btm 3 jts welded _____					
TD of hole _____ Set _____ Feet of _____ Inch _____ # Grade _____					
New-used csg. @ _____ with _____ sacks neat cement around shoe					
+ _____ sax _____ additives _____					
Plug down @ _____ (AM) (PM) Date <u>5/2 PS</u> <u>6" Hole</u>					
Cement circulated _____ No. of Sacks <u>25</u> <u>142</u>					
Cemented by _____ Witnessed by <u>125</u> <u>125</u> <u>317</u>					
Temp. Survey ran @ _____ (AM) (PM) Date _____ top cement @ _____					
Casing test @ _____ (AM) (PM) Date _____					
Method Used _____ Witnessed by _____					
Checked for shut off @ _____ (AM) (PM) Date _____					
Method used _____ Witnessed by _____					
Remarks: <u>TD 450 dry @ 7-200 - set w/ 38' hel. full w/ 203-07</u> <u>well to be plugged as follows.</u>					
<u>1. 25 sbs at T.D. 25 sax dumped w/ hel @ 4:00 PM.</u>					
<u>2. 15 sbs. at 200' (8-8-63)</u>					
<u>3. 5 sbs in surface</u>					

with mud between plugs

TD 442. Pulled 7" csg.
water within 150-200' of surface (8-9-63)
bridged hel @ 225-215 dumped 10 sax
" @ 55-50 " 5 sax
set marker w/ 5 sax NESEW 32-19-27
OK. When forms are in