

July 1, 1957

Magnolia Petroleum Company
Box 2406
Hobbs, New Mexico

Dear Sir?

I would like to inform you that we have not received an answer of our letter to you dated January 18, 1957, stating that our field Representative Bill Gressett checked your New Mex. "A", Well #3, in Section 32-19S-27E, and in doing so found that there is not a location on the Marker. The Plugging and Clean up job is satisfactory.

Also on your Ralph Nix #1 in Section 11-19S-26E, The Marker has not been cemented and it is lacking a $\frac{1}{4}$ Section on it.

Please inform us by mail when this work has been Completed.

If we can be of any assistance, please let us hear from you.

Yours very truly,

OIL CONSERVATION COMMISSION

M. L. Armstrong,
Supervisor, District No. 2

MLA/jn

1950. 1. 1950

Engineering Petroleum Company

Box 210

Yonkers, New York

Dear Sir:

I would like to inform you that we have not received an answer of our letter to you dated January 12, 1950, stating that our field representative Bill Bennett checked your New York, New York, in location 32-100-100, and in doing so found that there is not a location on the map. The map-plate and clean up for is satisfactory.

Also on your trip to the location 32-100-100, the Barker has not been located and is in fact a 2-1 location on it.

Please inform us if you find any more locations.

If we can be of any assistance, please let us hear from you.

Yours very truly,

WILLIAM B. BARKER

W. B. Barker
Representative, Division 2

WBB