	·					
	NI		CONSERVAT	ION CUMMISSION	Rok C-110 (Rev. Z460) 2 19-160	
	CERTIFIC	ATE OF CO		AND AUTHORIZY	KIIUN 22	
ORATION OFFICE				NATURAL GAS	JAN _ C. Dreice	
Company or Operator Kincald & Watson Dri		Lease Atlantic State ### ARTE Well No. 2				
Jnit Letter Section	Letter Section Township Ran			County Rddy		
Pool Rash Red Lake - Oter	1 17 28 Leke - Queen			Kind of Lease (State, Fed Fee)		
If well produces oil or cond give location of tanks		Unit Letter C	Section 1	Township 17	Range 28	
Authorized transporter of oil 📕 or condensate 🗌			Address (give address to which approved copy of this form is to be sent) The Parklen Corporation P. C. Box 4157			
The Formian C	irporation Is Gas Ac	tually Connecte	Pitiant.			
Authorized transporter of casing head g			Address (give address to which approved copy of this form is to be sent)			
Phillips Petroleum Company 7/60			Bartlesville, Oklahoma			
If gas is not being sold, give reasons a	and also explain its	present disposition:				
Change in Tr Oil	an sporter (check one Dry ead gas . 🔀 Conc	e) Gas	Change in Own Other (explain	ership	·	
Remarks Transporter in change	≥1 from Cacb	is Ferreirie.	, Înc. aite	et de Albedi		
The undersigned certifies that the	Rules and Regula		onservation Com	mission have been comp	lied with.	
Executed	l this the	day of		, 19		
OIL CONSERVA Approved by	TION COMMISSION			Rie Ha	(mic	
ML Osai	string		Title	allent		
Title OCL AND GAS INSPEC			Company Kincaid &	Watson Drilling	Company	
JAN 2 5 1961			Address P. O. Box) 1	36, Artesla, New 98	Mexico	