

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	
LAND OFFICE	☒
OPERATOR	☒

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501
MAR 23 1987
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-79

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG RALS TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator John A. Yates, Jr.	8. Farm or Lease Name State "A"
3. Address of Operator 105 South Fourth Street, Artesia, New Mexico 88210	9. Well No. 6
4. Location of Well UNIT LETTER P 990' FEET FROM THE South LINE AND 990' FEET FROM THE East LINE, SECTION 5 TOWNSHIP 19S RANGE 28E NMPM.	10. Field and Pool, or WHCat Artesia Qn Grbg. SA
15. Elevation (Show whether DF, RT, GR, etc.) 3545' DF	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug & abandon. Well has 8 5/8" csg set @ 470' w/50 sx cement, 4 1/2" csg set @ 2050' w/90 sx cmt., estimated top of cmt @ 1635'. Queen estimated at 1560-1590'. Propose to displace hole w/36 bbls mud. Spot 30 sx CL "C" w/4% CaCl₂ across perfs 1940-2016'. WOC and tag cement top. Will perforate 4 1/2" csg at 1600' and pump into perfs; if get circulation, will pump 50 sx Cl "C" if no circulation, will set 25 sx plug @ 1610'. Will perforate 4 1/2" csg @ 450' and spot 75 sx Cl "C". If csg is loose, will pull & lay down loose pipe. If csg is intact (but has hole) will pump about 65 sx Cl "C" in top of casing and in annulus, install dry hole marker and clean location for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie W. Williams TITLE Senior Engineer DATE 3-3-87
APPROVED BY Mike Williams TITLE OIL AND GAS ENGINEER DATE MAR 17 1987