

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.E.	
LAND OFFICE	
OPERATOR	/

JUN 01 1981

O. C. D.

5a. Indicate Type of Lease
State ☒ Free ☐
5. State Oil & Gas Lease No.
OG-272

SUNDY NOTICES AND REPORTS ON WELL ARTESIA, OFFICE
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO deepen OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☒	7. Unit Agreement Name
2. Name of Operator	East Millman Pool Ut TR 5
3. Address of Operator	8. Farm or Lease Name
SUN OIL COMPANY-MIDLAND-829445	
P.O. Box 1861	9. Well No.
Midland, Texas 79702	3
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER K, 1980 FEET FROM THE West LINE A. 1650 FEET FROM	Millman (Q-G) East
THE South LINE, SECTION 12 TOWNSHIP 19S RANGE 28E N.M.P.M.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ Convert to water injection	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU. Pull rods & pump, install BOP.
Tag btm & strap out of hole w/2 3/8" tbgs. GOI & clean out to 2294' PBTD.
Perf 2252-1702', 1JSP2F, 48 holes. RIH w/cup straddle pkrs on WS. acidize perforated intervals w/250 gals 15% NEHCL. POH w/pkr.
RIH w/pkr to 2294', circ well clean PU & set pkr 1600'. Swab well back.
POOH w/WS.
RIH w/5 1/2" pkr, nickel plated, set @2040'. Release from pkr & PO & LD WS.
RIH w/5 1/2" nickel plated dual hydraulic pkr w/15 jts 2 1/6" IJ IPC externally FG wrapped tbgs & straight pull overshot for OSTD below pkr. Set dual hydraulic pkr @1600'±. Hang long string in dual well head.
RIH w/nickel plated nipple 1 1/4" IJ 4' pup jt on 2 1/6" IPC tbgs w/bevelled collars.
Circ annulus w/pkr fluid. Latch short string into upper pkr. Hang upper tbgs in slips in dual well head. Install injection assembly.
Put on injection @max rate 200 BWPD & max TP 900#.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Loris Williams TITLE Sr. Accounting Assistant DATE May 27, 1981

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT 11 DATE JUN 02 1981

CONDITIONS OF APPROVAL, IF ANY: