

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

SEP 5 1980

O. C. D.

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. E- 7668

SUNDRY NOTICES AND REPORTS ON WELLS, OFFICE

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" FORM C-1011 FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Sun Oil Company	8. Form or Lease Name E. Millman Pool Ut. Tr 7
3. Address of Operator P. O. Box 1861 Midland, TX 79702	9. Well No. 1
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM TKE West LINE, SECTION 13 TOWNSHIP 19 S RANGE 28 E NMPM.	10. Field and Pool, or Wildcat Millman (Q-G), East
15. Elevation (Show whether DF, RT, GR, etc.) 3379' GR	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU. POH w/pump. Install BOP. Pull 2 3/8" tbq.
- RIH w/4 1/2" Pkr & SN on 2 7/8" tbq. to 2150'.
- Attempt to load hole w/35 bbls NE trtd KCL wtr.
- PU Pkr to 2117'.
- Spot 2 bbls acid 2116-2064', set Pkr @ 1920+.
- Acidz perfs 2064-2116' w/700 gals 15% NEHCL.
- Flush w/NE treated KCL wtr to perfs.
- Swab back load to determine production potential. POH w/Pkr.
- Load hole w/35 bbls NE treated KCL wtr.
- Perf 2054-2123 (27 holes)
- RIH w/4 1/2" Pkr & SN on 2 7/8" tbq.
- Attempt to load hole w/35 bbls NE treated KCL wtr.
- Pick up Pkr to 2124'. Spot 2 bbls acid 2123-2054'. Set Pkr @ 1920+.
- Acidz Perfs 2054-2123' w/3500 gals. 15% NEHCL.
- Flush w/NE treated wtr to perfs.
- Swab back load. Run Pkr thru Perfs & reset @ 1920'.
- Frac perfs 2054-2123' w/30,000 gals 2% KCL wtr & 39,750# Sand.
- Swab back to evaluate. CO as required.
- POH w/tbg. & Pkr. RIH w/2 3/8" tbq. to 1950'.
- RIH w/rod string & pump. POP & potential well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Doris Williams

TITLE Sr. Accounting Assistant

DATE 9-4-80

APPROVED BY W.A. Gresset

TITLE SUPERVISOR, DISTRICT II

DATE SEP 8 - 1980

CONDITIONS OF APPROVAL, IF ANY: