

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-015-02251
Indicate Type of Lease STATE ☒ FEE ☐
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name East Millman Unit
Well No. 149
Pool name or Wildcat Millman, YT-7R, East (46555)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
Name of Operator SDX Resources, Inc.	
Address of Operator PO Box 5061, Midland, TX 79704	
Well Location Unit Letter <u>B</u> <u>880</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>14</u> Township <u>19S</u> Range <u>28E</u> NMPM <u>Eddy</u> County	
Elevation (Show whether DF, RKB, RT, GR, etc.)	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐
 OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Casing Condition:

10-3/4" @ 423' w/75 sx. TOC calc @ surf
 4-1/2" @ 2287' w/300 sx. TOC est @ 900'
 Perfs: 1818' - 2112'

Propose to TA as follows:

Set CIBP @ 1750'. Circ & test. If csg test will circ, inhibited fl & run chart to TA well.

If not will P&A as follows:

Circ hole w/mud laden fl. Spot 10' sx on top of plug. Cut & pull 4-1/2" from 900' if possible. Spot 25 sx plug 950' - 850'. Spot 35 sx plug 473' - 373'. Spot 10 sx surf plug. Install marker & clean location.

TA9.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie A. Waters Title Regulatory Tech DATE 08-25-01

TYPE OR PRINT NAME Bonnie A. Waters TELEPHONE NO. 915/685-1761

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep ID DATE 4-15-02

CONDITIONS OF APPROVAL, IF ANY:

Hand copy to Follow -
 Faxed to SDX 4-15-02 -
 915-1685-0533

195

196

197

198

199

200

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-015-02251
Indicate Type of Lease STATE ☒ FEE ☐
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name East Millman Unit
Well No. 149
Pool name or Wildcat Millman, YT-7R, East (46555)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	
Name of Operator SDX Resources, Inc.	
Address of Operator PO Box 5081, Midland, TX 79704	
Well Location Unit Letter B 660 Feet From The North Line and 1980 Feet From The East Line Section 14 Township 19S Range 28E NMPM Eddy County	
Elevation (Show whether DF, FKB, RT, GR, etc.)	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☒	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Casing Condition:
10-3/4" @ 423' w/75 sx. TOC calc @ surf
4-1/2" @ 2287' w/300 sx. TOC est @ 900'
Perfs: 1818' - 2112'

Propose to TA as follows:

Set CIBP @ 1750'. Circ & test. If csg test will circ, inhibited fl & run chart to TA well.

Test csg. to 500' per 30 min - Chart test.

If well does not pass submit an Intent to P&A As Per 202.A.(1)

Give notice to P&A: Spot 10 on top of plug. Cut & pull 4-1/2" from 900' if possible. Spot 25 on plug 950' - 858'. Spot 35 on plug 473' - 873'. Spot 10 on surf plug. Install marker & clean location.

Give OCD Notice 24 Hrs Prior to Any work

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Osterwater TITLE Regulatory Tech DATE 08-25-01

TYPE OR PRINT NAME Bonnie Osterwater TELEPHONE NO. 915/885-1761

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep ID DATE 8-29-01

CONDITIONS OF APPROVAL, IF ANY:

