Submit 3 Copies to Appropriate District Office	State of New Mexico Eners, <i>J</i> inerals and Natural Resources Department				c15	For Re	m C-103 vised 1-1-89	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION 2040 Pacheco St.				N F	WELL API NO.	¥		
DISTRICT II Santa Fe, NM 87505					30-015-02287			
					and the type of Leas	STATE	FEE	
<u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410					sState Oil & Gas Lease No.			
SUNDRY NOTICES AND REPORTS ON WELLS								
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					⁷ Lease Name or Unit Agreement Name East Millman Unit			
Type of Well: OIL GAS WELL , WELL OTHER WIW								
sName of Operator V SDX Resources, Inc.					«Well No. 152			
sAddress of Operator PO Box 5061, Midland, TX 79704					⊮Pool name or Wildcat Millman Yts-7R (46555)			
Well Location		<u>,,,,,</u> ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Line and 6	660				
					Feet From The		Line	
Section 22	Township 19S			28E	NMPM	Edidy	County	
11 Check Appropriate Roy to Indigate Nature of Natice, Report, or Other Date								
11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:								
						ALTERING CA		
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILL	LING OP	vs.	PLUG AND AN		
PULL OR ALTER CASING			CASING TEST AND CEMENT JOB					
OTHER: Repair csg.	<u></u>	\mathbf{X}	OTHER:					
2Describe Proposed or Completed Operation work) SEE RULE 1103.	ns (Clearly state all pertinent details,	and give	pertinent dates, inclu	iding estin	nated date of starting	any proposed		
Flow back well & TOH w/PC tbg &	pkr							
TIH w/bit on 2-3/8" workstring & clean out well to 2380'.								
Set RBP @ appx 1600' & test w/pkr for hole. Depending on results will either squeeze hole or attempt to back off & replace top portion of 4-1/2" csg.								
Once csg tests ok - Pull RBP & LD	workstring.				1415			
Run AD-1 back to 1568' on 2-3/8"	PC & return well to injection.				। জ			
				OCD PEC	SEIVED IFTESIK			
I hereby certify that the information above is	; true and complete to the best of my		ge and belief.		and at a fact	DATE 02-	10-00	
		nr	LL		<u>();;; = </u>			
TYPE OR PRINT NAME (This space for State Use)						TELEPHONE NO.	<u></u>	

APPROVED BY MULCS LEPE field TITLE FIEld Rop I DATE 2/24/2000

* Notifie NMOCO to withers Repair questions

EMU # 152 660 FNL & 660'FEL Sec. 22 T19S R28E Edy Co., N.M.

Existing Condition:

12-1/2" hole to 465' with 465' of 10-3/4" csg cemented with 75 sxs. (TOC calculared at 100') 10" hole to 1350 & 8" to 1941' & 6" to 2542 with 2542' of 4-1/2" casing cemented with 400 sxs. (TOC by free point at 700'). OH 2542-2663 with BP at 2480. Perfs 2413-30 with CIBP 2380'. Perfs: 1669'-2178'.. 2-3/8" PC tubing at 1568' with baker AD-1.

Proposal:

- 1.) Flow back well and TOH with PC tubing and packer.
- 2.) TIH with bit on 2-3/8" workstring and clean out well to 2380'.
- 3.) Set RBP at ~ 1600' and test with packer for hole. Depending on results will either squeeze hole or attempt to back off and replace top portion of 4-1/2" casing.
- 4.) Once casing test OK: pull RBP and lay down workstring.
- 5.) Run AD-1 back to 1568 on 2-3/8" PC and return well to production. injection.