

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals, and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

NOV 17 1993

O.C.D.

WELL API NO. 30-015-0232

5. Indicate Type of Lease  
STATE ☒ FEE

6. State Oil & Gas Lease No.  
State 648 Milman 7 Rivers E.

7. Lease Name or Unit Agreement Name

State 648 Milman 7 Rivers E.

8. Well No.  
177

9. Pool name or Wildcat  
Milman 7 Rivers East

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
DEKALB Energy Company % Steve Smith

3. Address of Operator  
P.O. Box 10513, Bakersfield, CA 93389

4. Well Location  
Unit Letter B : 330 Feet From The North Line and 2310 Feet From The East  
Section 28 Township 19S Range 28E NMPM Eddy Cou

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3391' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/11/93 Move in and rig up Baber rig. Trip in hole with 2 3/8" tubing to 1161'. Pulled tubing to 1114' and equalized 35 sacks cement. Trip out of hole. Shut down for night.

11/12/93 Trip in hole and tag cmt. plug at 728'. Circulate hole with salt gel. Trip out of hole with tubing. Rig up wireline and shot 4 holes at 720'. Trip in hole with 4 1/2" cement retainer and set at 700'. Squeezed 25 sacks cement. Trip out of hole with tubing, rig up wireline. Shot 4 holes at 340'. Trip in hole with 4 1/2" cement retainer and set at 200'. Squeezed 25 sacks cement. Mixed 12 sacks cement and filled 4 1/2" and 7' casing. Rig down and move off location.

11/14/93 Restored location, installed well marker, and cleaned location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Steve Smith TITLE Agent DATE 11/15/93

TYPE OR PRINT NAME Steve Smith (805) 833-1032 TELEPHONE NO.

(This space for State Use)

APPROVED BY Johnny Rolunser TITLE 11-12-93 DATE