

Duffy & Wilson
Robinson Bro July 6.
State A#1

M-36-19-28

133/8 e 331' our records show 351' e

85/8 e 2400 we show 2087 Cal TOC 1705 with hole 1428'

5 1/2 e 9700' 2000' TOC e 8525'

Perfs e 9112-68

TOS e 315'

BOS e 800'

Delaware e 3085'

Bone Sp. e 4035'

2nd BS e 6890'

Wolf C e 9060'

Cisco e 9615'

Canyon e 9891'

Stw e 10160'

Set CIBPC Top of WC 8975' + cap 35' cont.

100' plug e Top of BS 4035' +

100' plug e TO Del 3085'

100' plug 50 in + out of 5 1/2' stub + tag

~~Ref at cut + pull 8578 e~~

Ref 85/8 e shoe + sponge leaning 100' inside

7 1/2" in hole 25 lb per blk 10 lb brace

PLUG AT TOC

PLUG AT BS + TOS

10 SX SURFACE

PLUG AT 6810 - > 2000' PLUG

Winchester Wellcamp

- 1 well file
- 2 assignments
- 3 7500.00 1 well bond / Bonding Co. 1961
- 4 Drilling procedure
- 5 Trg of note
- 6 Insurance

Well was spudded Oct 1 1961 drilled to
7329

Operator H N Lawrence Box 582 Russellville

Well P & A Dec 1961

Re-entering in 1965 & deepened to
10,500' by G C Williamson
Midland Texas
TD 9700'

Change of owner 2104 dated
July 1 1988 to Leroy S. Wilson
and Braunstein, passed title to the well to them.
Oil production ceased 3-1-73 when well
was reclassified as a gas well. I have been
unable to find any gas production. I have
not found any production under Bill Hamilton.