

Bill R Wilson State A # 1
M-36-19-28

Billy R Wilson contracted with ^{Roy Weyant} to plug the above captioned well. Mr. Weyant ~~engaged~~ ^{rigged up} Barber Well Service Feb 22, 1994. They bleed down the well, removed the belts & tried to unscrew the pbs, which would not come loose.

3-1-94 pulled out of hole with tbg but left the packer. Set CIBP @ 8975'

3-2-94 Cap CIBP with cement, weld on left sub, rig up csq jacks. Picked up on csq & csq was parted. Csq weight 40,000 lb. Csq parted at the slips & went down hole.

3-3-94 rig. up tools, pickup fish and pull out of hole with 2565' of 5 1/2" csq. Pick up tools & attempt to re-enter fish. Worked for 2 hrs but tool would not enter csq stub.

3-4-94 Worked for 2 hours with bent sub & tools, but could not re-enter. Mr. Weyant left the location with ^{leaving} 2450' of tbg in the hole & 350' in the derrick.

Mr. Guy Allen Baker talked to me about him taking over the well and dressing off the csq stub, re-enter the well & recomplete in the Bone Springs or DeCoursey. I told him we would have no problem with this if Mr. Wilson would make the assignment. Mr. Wilson called me later that day & said that he & Mr. Baker had made an agreement for Mr. Baker to take the well. We have not received change of operator from Mr. Baker.