


STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SAFETY	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	



Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection Well	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Herman J. Ledbetter ✓	5. State Oil & Gas Lease No. B 7717
3. Address of Operator P. O. Box 5879, Abilene, Texas 79608	7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>I</u> , <u>330</u> FEET FROM THE <u>East</u> LINE AND <u>1650</u> FEET FROM THE <u>South</u> LINE, SECTION <u>1</u> TOWNSHIP <u>19S</u> RANGE <u>29E</u> N.M.P.M.	8. Farm or Lease Name Leonard State
	9. Well No. 4
	10. Field and Pool, or Wildcat East Turkey Track Queen
15. Elevation (Show whether DF, RT, GR, etc.) 3407.6 G L	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Hook up cementer to oil string and squeeze down casing with Bradenhead open. When cement returns to surface via annulus between oil string and surface pipe, close in bradenhead and continue squeeze.
- Let cement set.
- Drill our cement in casing and test.

Originals Returned 6-5-86

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Herman J. Ledbetter TITLE operator DATE 5-20-86

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: