

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.

30-015-03548

Indicate Type of Lease

STATE ☒

FEE ☐

State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Lease Name or Unit Agreement Name

turkey Track Sec. 3

Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

Name of Operator
Web Oil Company

Well No.

8

Address of Operator

P. O. Box 1124, Artesia, NM 88211-1124

Pool name or Wildcat

Well Location

Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line

3 Section 19S Township 29E Range NMPM Eddy County

Elevation (Show whether DF, RKB, RT, GR, etc.)

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ANBANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 2941'

PBTD 2501'

8 5/8 @ 320 w/ 25 sx., 10" hole.

7" @ 2439, w/ 40 sx., 8" hole, .

8/10/54 CIBP Set @ 2200'

Top perms. 2084-2106

Proposal for plug and abandon.

1. Set CIBP @ 2025', load hole with plugging mud. Dump 40' Class "C" cmt. on top CIBP'

2. Perf. 7" @ 250' & 350'. RIH w/ packer to 750', Sqz. 50 sx. Class "C" cmt., WOC and pressure test. Sqz. w/ packer @ 250 w. 50 sx c.ass

"C", WOC and pressure test.

4. Spot 10 sx. surface plug.

5. Install dry hole marker and clean location.

2. Perf. 7" @ 1200' + 320'. Squeeze 100' cement Plugs inside + outside 7" casing. T&S Plugs.

4. Perforate 7" casing @ 50'. Circulate cement to surface inside + outside 7" casing.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE AGent

DATE 12-06-00

TYPE OR PRINT NAME Wayne Brooks

TELEPHONE NO. 915-580-7161

(This space for State Use)

APPROVED BY

mae S. [signature]

TITLE

Field Rep II

DATE

12/11/2000

CONDITIONS OF APPROVAL, IF ANY:

* Notify N.M.O.C.D. to witness Plugging operations.