Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT

## OIL CONSERVATION DIVISION

cl	51
----	----

P.O. Box 1980, Hobbs, NM 88240	40 Pacheco St.	i Dividioi	WELL API NO.				
DISTRICT II Santa Fe, NM 87505			31-01	5-03556			
P.O. Drawer DD, Artesia, NM 88210			sindicate Type of Lea	I <b>SC</b>	7		
DISTRICT III			01-4-014.0-1	STATE FEE	<u></u>		
1000 Rio Brazos Rd., Aztec, NM 87410			«State Oil & Gas Lea	se No.			
SUNDRY NOTICES AND REPO	RTS ON WELL	s	······································				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7Lease Name or Unit	Agreement Name			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)			Turkey Track Sec.3				
1Type of Well:							
O'L GAS WELL O							
AName of Operator			eWell No.				
Web Oil Company  3Address of Operator			2 ₅Pool name or Wildcat				
P. O. Box 1124, Artesia, NM 88211-1124		W-COLLING OF AANOCS	11				
4Well Location							
Unit Letter C: 660 Feet From The	North	Line and 1980	Feet From The	West Line			
3 Section 19S Townshin	29E Ra			Eddy o .			
Total Total	(Show whether DF, Ri	inge KB. RT. GR. etc.)	NMPM	Eddy County			
	3419						
11 Check Appropriate Box t	o Indicate Nati	ure of Notice. Rep	ort. or Other D	)ata			
NOTICE OF INTENTION TO:	•	SEQUENT REPORT OF:					
			LQUENTIAL	PORTOR.			
PERFORM REMEDIAL WORK	ANDON X	REMEDIAL WORK		ALTERING CASING			
TEMPORARILY ABANDON CHANGE PLAN	is [	COMMENCE DRILLING OP	NS.	PLUG AND ANBANDONMENT	L		
PULL OR ALTER CASING CASING TEST AND CEME			ALL YOB				
OTHER:		OTHER:		Į			
12Describe Proposed or Completed Operations (Clearly state all pertin	port datails, and give a	pathoat dates feel visa sati	maked data of starting				
work) SEE RULE 1103.	ent details, and give p	eraren Gales, including esa	mateu cate or starmy	any proposed			
TD 2268'							
PBTD 2168' 8 5/8 @ 380', 10" hole cmt. w/ 50 sx.				12345678			
8 5/8 @ 380', 10" hole cmt. w/ 50 sx.  7 @ 2040, 8 " hole, cmt. w/ 65 sx.  OH to 2112'  Proposal for plug and abendon							
OH to 2112'			(Sign	A 33			
Proposal for plug and abandon.				Office of the second			
1. Set CIBP @ 2000', load hole with plugging mud. S	pot 30 sx. Class "	C" cmt. from 2000' to 1	1860'.	OCD AD LOS			
2. Perf 7 " csg. @ 1200". & 375". Set Packer @ 1100", Sqz. 75 sx class "C" cmt							
3. Sqz. with packer 50 sx.@ 275', circ. to surface.  4 <del>. Spot 10 sx. surface plug.</del>							
Proposal for plug and abandon.  1. Set CIBP @ 2000', load hole with plugging mud. Spot 30 sx. Class "C" cmt. from 2000' to 1860'.  2. Perf 7 " csg. @ 1200'. & 375". Set Packer @ 1100', Sqz. 75 sx class "C" cmt  3. Sqz. with packer 50 sx.@ 275', circ. to surface.  4. Spot 10 sx. surface plug.  5. Install dry hole marker and clean location.  7. Perf. 7" csg. > 1200 x 430. Squeege 100 cenent Plugs inside routside							
Z Pect. 7" csg 5 1200 x 430. Squeen	ie 100 ceneñ	TPlucs insider	outside	182028323232			
TAG Place		,					
4. Pert 2"cs: 5 50. Erculate cemen	T to surface	e inside tout	side D' Co	1.			
4. Per 1. 2"cs; 50 50. Execulate cement to surface inside + outside?" csq.  Thereby certify that the information above is true and complete to the best of my knowledge and belief.							
SIGNATURE	T)T  6	E AGent		DATE 12-06-00			
	71166	*		DAIC TE OF OF			
TYPE OR PRINT NAME Wayne Brooks				TELEPHONE NO. 915-580-7161			
(This space for State Use)							
200 15 1000 N° 00		FILO #		12/11/200			
APPROVED BY Mare Still field	TITLE	: FIEW TOPO IL		DATE 12/11/2000			
* Notifie N.M.O.C.D to witness Plugging Operations							
TNOTITIE N.M.O.C.D TO WITTES !		14110/13					
	•						