

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/ ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO CONSERVATION COMMISSION

MAY 19 1977

O. C. C.

ARTESIA, OFFICE

SUNDARY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-

2. Name of Operator D. R. Clary ✓

3. Address of Operator P.O. Box 1267 Odessa, Texas 79760

4. Location of Well
 UNIT LETTER H 1980 FEET FROM THE North LINE AND 660 FEET FROM
 THE East LINE, SECTION 3 TOWNSHIP 19S RANGE 29E NMPM.

5a. Indicate Type of Lease
 State ☒ Fee ☐

5. State Oil & Gas Lease No.
B-8876-9

7. Unit Agreement Name
Turkey Track
Sec. 3 Unit

8. Farm or Lease Name
Turkey Track
Section 3 Unit

9. Well No.
9

10. Field and Pool, or Wildcat
Turkey Track Q-Grb.

12. County
Eddy

15. Elevation (Show whether DF, RT, CR, etc.)
GLE - 3403

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <u>D/O plugs & recomplete in same</u> <input checked="" type="checkbox"/> <u>pay.</u>	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Deepening operations started on 5/1/77. The cast iron plug at 2365 was drilled out and the well cleaned to 2464. Deepening of the well proved unsuccessful as the well was shot with nitro on completion and the shot hole continue to cave in making drilling imposible. After four days of drilling we actually lost four feet of hole. The operation was suspended and the well was restored to production. The well is presently unloading water lost during drilling operations.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE P.E. - Agent DATE 5/16/77

APPROVED BY [Signature] TITLE SUPERVISOR, DISTRICT II DATE MAY 20 1977

CONDITIONS OF APPROVAL, IF ANY: