

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-015-03558
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name Turkey Track Sec.3
Well No. 1
Pool name or Wildcat Turkey Track SB/R-6-SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
Name of Operator Web Oil Company	
Address of Operator P. O. Box 1124, Artesia, NM 88211-1124	
Well Location Unit Letter B : 660 Feet From The North Line and 1980 Feet From The East Line 3 Section 19S Township 29E Range NMPM Eddy County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3411 GR	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 3273'
PBD 2452'
8 5/8 @ 327 w/ 25 sx., 10" hole cmt.
7 @ 2129, w/ 33 sx., 8" hole, cmt. w/ 65 sx.
5 1/2 @ 2354 w/ 18 sx, 5 1/2 csg. pulled, Top of 5 1/2 @ 2109'
cmt. plug @ 2452'

Proposal for plug and abandon.

- Set CIBP @ 2060', load hole with plugging mud. Spot 30 sx. Class "C" cmt. from 2060' to 1920'.
- Perf 7" csg. @ 1200' & 375". Set Packer @ 1100', Sqz. 75 sx class "C" cmt.
- Sqz. with packer 50 sx. @ 275', circ. to surface.
- Spot 10 sx. surface plug.
- Install dry hole marker and clean location.

4. Perf. 2" csg. @ 50'. Circulate cement to surface. Inside + Outside 2" csg.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE **AGent** DATE **12-06-00**

TYPE OR PRINT NAME **Wayne Brooks** TELEPHONE NO. **915-580-7161**

(This space for State Use)

APPROVED BY maelstuffer TITLE Field Rep. II DATE 12/11/2000

CONDITIONS OF APPROVAL, IF ANY:

* Notify N.M.O.C.D. to witness Plugging Operations