

12. Describe Proposed or Completed Operations (cont)

8. TIH w/gun & perforated @ 1068'. TOH w/gun. TIH w/pkr & set @ 673'. Tried to pump into perfs w/1500# but couldn't. TOH w/pkr (called OCC for instructions).
9. TIH w/gun & shot 4 holes @ 1000'. TOH w/gun. TIH w/pkr and set @ 673'. Tried again to pump into perfs w/1500# but could not. TOH w/pkr. TIH w/tbg open ended to 1147'.
10. Spotted 50sx (Neat) plug. TOH w/tbg.
11. TIH w/perf gun & shot 4 holes @ 235'. TOH w/gun. TIH w/pkr to 197', but wouldn't set. Moved pkr to 166', but wouldn't set. Moved pkr down to 228' but wouldn't set (pipe was too ratty). TOH w/laying down pkr. TIH w/tbg open-ended to 254'.
12. Spotted 50sx plug (w/3% CaCl). WOC 1 hr. TIH w/sand line & tagged up @ 138'. TOH. TIH w/4 jts (124').
13. Spotted 50 sx plug (w/3% CaCl). WOC 1 hr. Tagged up on sand line @ 128'. TOH. TIH w/tbg to 124'.
14. Spotted 35 sx plug; did not circ. TOH w/tbg. SD f/Sunday.
15. TIH w/sand line & tagged up @ 110'. TOH. TIH w/tbg to 93'.
16. Spotted 35sx plug (Class C w/3% CaCl, 2sx multi-seal + 1sx flocele. WOC 1½ hrs. TOH w/tbg. Tagged up w/sand line @ 110'. TOH. TIH w/3 jts.
17. Spotted 35sx plug (Class C w/3% CaCl + 3sx flocele. TOH w/tbg. WOC 1½ hrs & tagged up @ 43'. TIH w/1 jt.
18. Loaded hole w/13sx Class C w/3% CaCl. Pumped 7sx to pit. RDPU. Clean location.
19. Set dry hole marker.
20. Plugged and Abandoned.