

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION

P. O. BOX 208  
SANTA FE, NEW MEXICO 87501

RECEIVED BY  
AUG 27 1984  
O. C. D.  
ARTESIA OFFICE

Form C-103  
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER- P&A

Name of Operator  
John A. Yates

Address of Operator  
207 South 4th St., Artesia, NM 88210

Location of Well  
UNIT LETTER D 330 FEET FROM THE North LINE AND 330 FEET FROM  
THE West LINE, SECTION 18 TOWNSHIP 19S RANGE 29E N.M.P.M.

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
E-7834

7. Unit Agreement Name

8. Farm or Lease Name  
Campbell-Gwaltney

9. Well No.  
1

10. Field and Pool, or Wildcat  
Palmillo Seven Rivers

12. County  
Eddy

15. Elevation (Show whether DF, RT, GR, etc.)  
3386' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

INFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

ULL OR ALTER CASING ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged well as follows: Pulled rods and tubing. RIH and cleaned hole to 2148'. Spot cement plug at 2148' w/75 sx Class "C". Pulled tubing to 1200' and circulated hole, 1 sx cement to surface. POOH. Set CIBP at 1200'. RIH with tubing to 1187'. Spot 40 sx Class "C" cement plug (est. top of cement at 610'). Perforated 4½" casing at 375' w/4 holes, set cement retainer at 300', sting tubing into retainer and squeezed w/150 sx Class "C" cement to surface in 8-5/8" casing. Pull out of retainer and filled 4½" casing w/35 sx Class "C". Installing dry hole marker. Witnessed by Mr. Larry Brooks, NMOCD, Artesia.

POST FD-2  
9-7-84  
PJA

5. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Larry Brooks TITLE Production Supervisor DATE 8-24-84

PROVED BY Larry Brooks TITLE Geologist DATE 9/17/84

CONDITIONS OF APPROVAL, IF ANY: