July 3, 1962

fejss Setroleum Company 525 Sidland Savings - Loan Sldg. Fidland, Sexes

> Re: Sinclair State A So. 1-8 Snit F, 18-198-292 Redy County, "ew sexico

Dear Sirs:

A recent field inspection of the above location s ows that the dry hole marker reads SW SW 18-19-29, but should read SW NW, also there were the down wires which need to be cut or pulled.

To complete the filing of said well we need Form U-103 plugging report.

Please notify this office when the necessary work has been done, so that we can make the final field inspection of the abandoned location.

Very truly yours,

OIL RESERVATION CONLISSION

E. L. Armstrong Supervisor, District 2

IA/jw

ಸಂಪರ್ಧ ಸಂಪ್ರದೇಶದ ನಿರ್ದೇಶನ ನಿರ ಪ್ರದೇಶನ ನಿರ್ದೇಶನ ನಿರ್ ಕೆ ಮಾಡಿ ಕಾರ್ಯವರ್ಷ ನಿರ್ದೇಶನ ನಿರ

ార్ స్పోటింగ్ సార్లో సార్థించిన సార్థించిన సార్థి కి.మీ. సినిమీ కి.మీ. కార్ కి.మీ. సార్థించిన సార్థించిన సార్థ ఈ సార్థించిన సార్థించిన సార్థి ప్రత్యేషన్ని సార్థి ప్రత్యేషన్ని సార్థించిన ప్రత్యేషన్ని ప్రత్యేషన్ని సంస్థించిన సార్థించిన సార్థించిన సార్థి పోటించిన సార్థి పోటించిన సార్థించిన ప్రత్యేషన్ని ప్రత్యేషన్ని సార్థించిన ప్రత్యాత్

್ರಾ. ಸ್ಥಾನಿಗಳು ಸಂಸ್ಥೆ ಸಂಸ್ಥೆ ಕಾರ್ಯಕ್ಷೇತ್ ಕಾರ್ಯಕ್ಷಿಗಳು ಸಂಸ್ಥೆ ಸೇವಿ ಸಂಸ್ಥೆ ಸೇವಿ ಸಂಸ್ಥೆ ಸೇವಿ ಸಂಸ್ಥೆ ಸಂಸ್ಥೆ ಸೇವಿ ಸಂ ಸ್ಥಾನ್ ಸ್ಥೆ ಸಿಲ್ಲಿ ಸ್ಥಾನ ಕಾರ್ಯಕ್ಷೇತ್ ಸಂಸ್ಥೆ ಸ್ಥೇನ್ ಸ್ಥೆ ಕಾರ್ಯಕ್ರಿಸಿದ್ದ ಸ್ಥೆ ಸಿಲ್ಲಾ ಸ್ಥಾನಿಸುವ ಸೇವಿ ಸಿಲ್ಲಿ ಸಿಲ್ಲ ಸ್ಥಾನಕ್ಕೆ ಸಿಲ್ಲೇ ಸ್ಥೇಟ್ ಕಾರ್ಯಕ್ಷೇತ್ ಸಿಲ್ಲಿ ಸಿರ್ವೇಶ್ ಸಿಲ್ಲಿ ಸಿಲ್ಲಿ ಸಿಲ್ಲಾ ಸಿಲ್ಲಿ ಸಿಲ್ಲಾ ಸಿಲ್ಲಿ ಸಿಲ್ಲಿ ಸಿಲ್ಲಿ ಸಿಲ