			c15
ubmit 3 Copies State of New Mexico Appropriate Energy, Minerals and Natural Resources Departmen			Form C-103 Revised 1-1-89
District Office OIL CONSERVATION DIVISION			
1625 N. French Drive, Hobbs. NM 88240 2040 South Pacheco	· · ·	WELL API NO.	
Santa Fe, New Mexico 8		30-015-03612 5. Indicate Type of Lease	
DISTRICT II 811 S. First Street, Artesia, NM 88210		STATE	<b>X</b> FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	1121374157613	5. State Oil & Gas Lease No. VB-0158	
SUNDRY NOTICES AND REPORTS ON WE			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPEND DIFFERENT RESERVOIR. USE "APPLICATION FOR PERA (FORM C-101) FOR SUCH PROPOSALS)	ATT CALLUG BACK TO AND	7. Lease Name or Unit Agreement Nar	ne
1. Type of Well:     OIL     GAS       WELL     X     WELL	ESIA AU	Chaparral State	•
2. Name of Operator	12850515850	8. Well No.	
STRATA PRODUCTION COMPANY		#2	
3. Address of Operator P.O. BOX 1030, ROSWELL, NEW MEXICO 88202-1030		9. Pool Name or Wildcat Und Winchester Bone Spring	
4. Well Location Unit Letter D : 660 Feet From The North		660 Feet From The	West Line
Section 32 Township 19 South 10. Elevation (Show whether DF, R 3309		i <u>t nmpm Eddy</u>	County
11.         Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data           NOTICE OF INTENTION TO:         SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT X			
PULL OR ALTER CASING CASING TEST AND CEMENT JOB			
OTHER:	OTHER:		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103			
<ul> <li>09/11/00: MIRU.</li> <li>09/12/00: NU BOP. TIH with tubing.</li> <li>09/13/00: Set 25 sack plug at 7125' with Class "C" cement. WOC 3 1/2 hours. Tag TOC at 6935'. Set retainer at 4965'. Squeeze with 75 sacks Class "C" Neat cement with 35' of cement on top of retainer.</li> </ul>			
09/14/00: Set retainer at 3450'. Squeeze with 75 sacks Class "C" Neat cement with 35' of cement on top of retainer. Set 150' plug in and out of 7" casing stub at 3000' with 45 sacks Class "C" cement. WOC 4 hours. Tag TOC at 2820'.			
09/15/00: Set 100' plug at 1050' with 45 sacks Class "C" cement. WOC 4 hours. Tag TOC at 930'. Set 100' plug at 435' with 45 sacks Class "C" cement. WOC 4 hours. Tag TOC at 300'. Set 10 sack plug at Surface with Class "C" cement. Release rig. Well Plugged and Abandoned. Prep to set Dry Hole Marker. Operations			
witnessed by OCD representative. 11/15/00: Cut off wellhead and deadman. Set Dry Hole Marker. Fill cellar and clean location.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Carol J. Darcia TITLE PRODUCTION RECORDS MANAGER DATE 11/15/00			
TYPE OR PRINT NAME CAROL J. GARCIA TELEPHONE NO 505-622-1127			
APPROVED BY APPROVAL, ANY:	ld Rep 1	DATE	11-22-00

.