

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION
FEB 18 1970
O. C. C.
ARTESIA, OFFICE

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-7256
7. Unit Agreement Name
8. Farm or Lease Name
9. Well No.
10. Field and Pool, or Wildcat
12. County

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input checked="" type="checkbox"/>
2. Name of Operator Ralph Mix and Jerry Curtis
3. Address of Operator P.O. Box 617, Artesia, New Mexico 88210
4. Location of Well UNIT LETTER <u>K</u> , <u>1000</u> FEET FROM THE <u>South</u> LINE AND <u>1747</u> FEET FROM THE <u>West</u> LINE, SECTION <u>6</u> TOWNSHIP <u>19N</u> RANGE <u>25E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3300' C. 1.

7. Unit Agreement Name
8. Farm or Lease Name
9. Well No.
10. Field and Pool, or Wildcat
12. County

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-23-68 - Moved in rig, set and pulled rods and to the
 ran tubing 130' to total depth, 225' and added 20 sacks cement plug
 muded hole with heavy mud to surface.
 Pulled tubing and shot 41' casing off. 724' and pulled
 ran tubing to 735' and pumped in 20 sacks cement plug in and out of stub
 of 41' casing.
 Spotted 20 sacks cement plug in shoe joint of 1-3/4" 2-5'
 Set regulation marker with 10 sacks cement and cleared location.
 Finished 7-30-68

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>Ralph Mix</u>	TITLE <u>Co-owner</u>	DATE <u>2/17/70</u>
APPROVED BY <u>B. L. H. H. H.</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>MAR 10 1970</u>
CONDITIONS OF APPROVAL, IF ANY:		