

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM-06766

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or recomplete a well back to a different reservoir.
Use APPLICATION FOR PERMIT TO DRILL (Form 5-532) for such proposals.

1.

OIL ☒ GAS ☐ OTHER ☐

MAR 3 1980

RECEIVED

2. NAME OF OPERATOR

GULF OIL CORPORATION

O. C. D.

FEB 29 1980

3. ADDRESS OF OPERATOR

P.O. Box 670, Hobbs, NM 88240

ARTESIA, OFFICE

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

4. LOCATION OF WELL (Report location clearly and in accordance with any local requirements.)

See also space 17 below.
At surface

2310' FNL & 660' FWL

9. WELL NO.

104

10. FIELD AND POOL, OR WILDCAT

No. Hackberry Yates

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Unit E

Section 24-T19S-R30E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3267' CL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other) Repair csg leaks

XX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2000' TD. 1961' PB. POH w/rods & pmp. Set RBP @ 1775' & cap w/10' frac sand. Set cmt rtmr @ 1445'. Squeeze hole @ 1480' w/50 sx Class "C" cmt w/0.5% Halad-9. Rvrs cut excess cmt. Set cmt rtmr @ 640'. Squeeze hole @ 677' w/50 sx Class "C" cmt w/0.5% Halad-9. Rvrs out excess cmt. Drill out both cmt rtnrs & cmt plugs to RBP @ 1775'. Set pkr @ 1445'; test squeeze to 500#. Recover RBP & set @ 725'. Set pkr @ 600'. Test squeeze to 500#. Recover RBP. Run rods & pmp & hang well on.

18. I hereby certify that the foregoing is true and correct

SIGNED

N. B. Liles, Jr.

TITLE Area Engineer

DATE 2-28-80

(This space for Federal or State office use)

GEORGE H. STEWART

APPROVED BY

TITLE

DATE

FEB 29 1980

CONDITIONS OF APPROVAL, IF ANY: