.m 3160-5 ugust 1999)

UNITEL 'ATES

	0	il C	J. 18	S.	FORM A
ı	M	וח	רוּוּע	ist.	2 Expires Nove

APPROVED . 1004-0135 ember 30, 2000

DEPARTMENT OF THE INTERIOR

gust 1999)	EPARIMENT OF THE	INTERIOR	ľ	7.171. DIV	tuist. 2				
•	BUREAU OF LAND MAN	AGEMENT 1	30.	I W. Grai	he Ave	Seriel d	⅓ o.		
CHADE	ANOTICES AND DED	OPTS ON WELLS	ΟO	tooin NIA	0001	10	LC029389A		
SUNDH	NOTICES AND REPOSE S form for proposals to	onis dil veces	"Ar	tesia, iviv	1,005	an All	ottee or Tribe Name		
Do not use this	is form for proposals to II. Use Form 3160-3 (AP	PD) for such proposals	3.		0. 11 1	w., <i>1</i> w.			
abandoned we	n. 030 / 0//// 0/00 0 (
	IDLICATE Other inst	ruotione on reverse	eida		7. If Unit	t or CA	/Agreement, Name as	nd/or No.	
SUBMIT IN TRI	PLICATE - Other insti	IUCIIOIIS OII TEVELSE	3140		ļ				
							-		
Type of Well		- -,	- -v			8. Well Name and No.			
Oil Well Gas Well	Other	<u></u>				Edwards Federal #3			
Name of Operator						9. API Well No.			
Kaiser-Francis Oil	Company					30-015-05501 10. Field and Pool, or Exploratory Area			
Address		3b. Phone No. (include							
P.O. Box 21468, Tu	ılsa, OK 74121-146	8 918-491-431	4		10. Field	and ro	or exploratory An	a Ougan	
Location of Well (Footage, Sec.	. T., R., M., or Survey Descripti	on)					ates 7 River	Creshure	
Excusion of view (consider)					11. Count	ty or P	arish, State	Grayburg	
							_		
NE SE (1650' FSL 8	, 990' FEL) of Sec	. 9-18S-31E			Edd	ly/M	<u> </u>		
NE SE (1050 185 6		TO INDICATE MATE	DE O	ENOTICE R	FPORT (OR O	THER DATA		
12. CHECK AP	PROPRIATE BOX(ES)	TO INDICATE NATU	KE U	F NOTICE, N					
				F ACTION				1	
TYPE OF SUBMISSION							W Chur Off		
	Acidize	Deepen		Production (Star	n/Resume)	u			
Notice of Intent	Alter Casing	Fracture Treat		Reclamation		u	Well Integrity		
	Casing Repair	New Construction		Recomplete			Other		
Subsequent Report	I ==	Ξ	$\overline{\Box}$	Temporarily A	bandon				
	Change Plans		7	Water Disposal					
Final Abandonment Notice Describe Proposed or Complete	Convert to Injection	Plug Back	u						
2. Set 25 sx cmt 3. Cut off 4½" c 4. Set 100 sx cm 5. Perf 8 5/8" c 6. Pump 125 sxs 7. Set 20 sx cmt	40' & dump 3 sxs: plug from 2000'-casing @ 900' & POnt plug from 950'-casing @ 200'. Secont down the & cit surface plug.	cmt on top. 1900'. 00H. 750'.	8" c	asing to	surface		SPROV	ED	
4. I hereby certify that the forego	oing is true and correct						TES EARYA	K SINGSER	
Name (Printed/Typed)						TROLLUM EM	(181.4.18		
Charlotte Van Wa	1kenburg	Title	Te	chnical Co	ordinal	tor			
Signature O	Diek.	Date Date	2/0	6/02					
	THIS SPACE	E FOR FEDERAL OR	STAT	E OFFICE US	SE				
			Title			Dat	е	· 	
certify	re attached. Approval of this	notice does not warrant or	Office	;			·:•		
Accepted for reco	rd			wingly and willfu	illy to make t	to any	department or agency	of the United	

Title 1 States

FEB 19 2002

te it a crime for any person knowingly and willfully to make to any department or agency of the United as to any matter within its jurisdiction.