

William A. & Edward R. Hudson

Shugart (A) #1

AFTER

Perforate $5\frac{1}{2}$ & $8\frac{3}{8}$ casing at 60' encasement between $5\frac{1}{2}$ & $8\frac{3}{8}$
 $8\frac{3}{8}$ open hole leave $5\frac{1}{2}$ FHL

$8\frac{3}{8}$ at 743' cmt. w/ 200' xs calc. Surface
Perforate $5\frac{1}{2}$ casing at Top of Salt 840' squeeze w/ 50' xs
Cement. Tag cement inside $5\frac{1}{2}$ casing at 650'

Perforate $5\frac{1}{2}$ casing at base of Salt 1920'
squeeze w/ 50' xs cement 100' cement inside casing

Set $5\frac{1}{2}$ C.I.B.P. at 3250' CAP w/ 35' cement

Perforations 3285'-3329'

$5\frac{1}{2}$ C.I.B.P. at 3405' CAP w/ 20' cement 1976

Perforations
3782-3792

$5\frac{1}{2}$ C.I.B.P. at 3894' CAP w/ 35' cement 1961

Perforations
3936-4020

$5\frac{1}{2}$ 4053' cmt. w/ 1200' xs calc. Surface

T.D. 4072'

