GEOLOGIC. SUNDRY NOTICES ANI (Do not use this form for proposals to drill or Use "APPLICATION FOR PH 1. OIL CAS	THE INTERIOR (Other ine AL SURVEY D REPORTS ON WELLS		Form approved, Budget Bureau No. 42-R 5. LEASE DESIGNATION AND SERIAL
GEOLOGIC. SUNDRY NOTICES ANI (Do not use this form for proposals to drill or Use "APPLICATION FOR PH 1. OIL CAS	AL SURVEY		5. LEASE DESIGNATION AND SERIAL
SUNDRY NOTICES ANI (Do not use this form for proposals to drill or Use "APPLICATION FOR PH 1.	D REPORTS ON WELLS		<u>~</u>
(Do not use this form for proposals to drill or Use "APPLICATION FOR PH 1. OIL CAS	D REPORTS ON WELLS		6. IF INDIAN, ALLOTTEE OR TRIBE N
			C. IF INDIAN, ALLOTTER OR TRIBE
	ERMIT—" for such proposals.)	t reservoir.	이 가슴 바람이 가슴이 가슴다. 것은 20명 - 나라 가슴 가슴 가슴
	RECEIVED BY		7. UNIT AGBREMENT NAME
WELL WELL OTHER			
Marathon Oil Company	SEP 13 1983		8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR	O. C. D.		9. WELL NO.
P.O. Box 2409, Hobbs, New Mex	TTO APTESIA OFFICE		3 <u>0 2 3 1 4 5 5 0</u>
 LOCATION OF WELL (Report location clearly and in a See also space 17 below.) At surface 	.co.adones with any State requirement	fs.•	10. FIELD AND POOL, OR WILDCAT North Shugart Yates-
		10001 6	Rivers Queen- Graybu II. SEC., T., R., M., OB BLE, AND
Unit Letter J, 1980' fr from the East line, Sec			SURVEY OR AREA
<u>31E, NMPM</u>		hange	Section 10, T18S, R3
	NS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH 13. STATE
	8; DF 3727		Eddy
16. Check Appropriate Bo	ox To Indicate Nature of Notic	e, Report, or Of	ther Data
NOTICE OF INTENTION TO:	1	SUBSEQUE	NT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER	CASING WATER SH	UT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE COMP	PLETE FRACTURE	TREATMENT	ALTERING CASINO
SHOOT OR ACIDIZE ABANDON* REPAIR WELL CHANGE PLANS		OR ACIDIZING	ABANDONMENT
(Other)	(Other)(Nor:	E : Report results c	f multiple completion on Well
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clear proposed work. If well is directionally drilled, g	ly state all pertinent details and give	a nortinent dates i	tion Report and Log form.) =
Released packer and bridge plug with production equipment and a pumping to battery.			h back in the hole with the ho
			(1) Complete the cubication and any sector of the cubication of

See Instructions on Reverse Side