

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYN. M. O. C. C. COPY
SUBMIT IN T Llicate*
(Other instru s on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER P & A.		5. LEASE DESIGNATION AND SERIAL NO. LC 047633 (a)	
2. NAME OF OPERATOR Atlantic Richfield Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 1978, Roswell, New Mexico 88201		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 1980' FEL (Unit Letter G)		8. FARM OR LEASE NAME E.M. Swearingen "A"	
14. PERMIT NO.		9. WELL NO. 4	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3722' GR		10. FIELD AND POOL, OR WILDCAT Shugart	
		11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA Sec. 14, T-18S, R-31E	
		12. COUNTY OR PARISH Eddy	
		13. STATE N.M.	

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input checked="" type="checkbox"/>
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well has been plugged & abandoned in the following manner:

Spotted 30 sk Class "A" cement plug 3310-3180'. Shot off 7" casing at 1029' & 930', could not pull free. Csg pld free with third shot @ 894' WLM. Pulled 40 jts 7" casing. Set 60 sk Class "A" cement plug 1045-843' (in and out of 7" stub, and across 8-5/8" shoe @ 885'); set 10 sk cement plug in top of well. Salt gel mud was used to spot all plugs. 8-5/8" casing string remains intact. Installed dry hole marker and levelled location. Well P & A 6/23/70.

Your office will be notified when location is ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED P.L. BEEKMA TITLE Dist. Drlg. Supervisor DATE 6/24/70

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side