

Copy to § 3.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

9. LEASE DESIGNATION AND SERIAL NO.
LC 047633 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
~~Swearingen~~ Swearingen "B"

9. WELL NO.
2

10. FIELD AND POOL, OR WILDCAT
Shugart

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 14, T-18S, R-31E

12. COUNTY OR PARISH
Eddy

13. STATE
N.M.

1. OIL WELL GAS WELL OTHER P & A

2. NAME OF OPERATOR
Atlantic Richfield Company ✓

3. ADDRESS OF OPERATOR
P. O. Box 1978, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

660' FNL & 660' FWL (Unit Letter D)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3713' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well has been plugged & abandoned in the following manner:

Spotted 30 sk Class "A" cement plug 3260-3390'; 30 sk Class "A" cement plug 2480-2610'; Shot 7" casing off @ 1416', pulled 45 jts 7" casing. Spotted 30 sk Class "A" cement plug half in & half out of 7" casing stub @ 1412'. Spotted 30 sk Class "A" cement plug half in & half out of 8-5/8" shoe @ 797'. Used 9#/gal salt gel mud to spot all plugs. Set 10 sk Class "A" cement plug in top of well and erected dry hole marker. 8-5/8" casing remains intact. Well plugged & abandoned 6/14/70.

POW

Your office will be notified when location is ready for inspection.

RECEIVED
RECEIVED
SEP 25 1970
JUN 23 1970
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *A. L. Beekma*

TITLE District Office Supervisor DATE 6/17/70

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

APPROVED

A. L. Beekma
A. L. BEEKMA

*See Instructions on Reverse Side