

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 047633(a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

M. Swearingen "A"

9. WELL NO.

10. FIELD AND POOL OR WILDCAT

Shugart

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 14, T-18S, R-31E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☐ OTHER WIW - P & A

2. NAME OF OPERATOR

Atlantic Richfield Company ✓

3. ADDRESS OF OPERATOR

P. O. Box 1978, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1980' FNL &amp; 660' FEL (Unit Letter H)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3730' GR

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well has been plugged and abandoned as follows:

Set CIBP @ 3370'. Spotted 25 sk Class "A" cement plug from 3250-3370'. Shot off 7" casing @ 1100'. Pulled 35 jts of 7" 20# J-55 casing. Spotted 65 sk Class "A" cement plug from 897-1147' (in and out of 7" stub and across 8-5/8" casing shoe @ 950'). Set 10 sk cmt plug 15' to surface. Erected dry hole marker. 9#/gal salt gel mud was used to spot all cement plugs. 8-5/8" casing remains intact. Well P & A 7/1/70.

Your office will be notified when location is ready for inspection.

RECEIVED

SEP 25 1970

RECEIVED

JUL 10 1970

18. I hereby certify that the foregoing is true and correct.

SIGNED

D. L. BEEKMA

TITLE

Dist. Dir. Supervisor

DATE

7-8-70

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side