

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRY
(Other instructi
verse aide)

CATE*
on re

form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

4/5F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ Water Injection

2. NAME OF OPERATOR

William A. & Edward R. Hudson

3. ADDRESS OF OPERATOR

P.O. Box 9, Maljamar, New Mexico 88264

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' from North and East lines,
Sec. 15-18S-31E

AUG 07 '89

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

O. C. D.

3698' DF

ARTESIA, OFFICE

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☒
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐
☐

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.) *

We propose to plug and abandon this well as follows:

Set a "cast iron" bridge plug in 5-1/2" casing at 3265',
spot 50' cement on top of bridge plug, load hole with salt gel mud,
perforate 5-1/2" casing at 800' with 4 shots, set cement retainer.
in 5-1/2" casing at 750', circulate cement to the surface, place
150' cement on top of retainer, load hole with fresh water, place
50' cement at the surface, install dry hole marker with well data,
clean location and reseed according to BLM regulations.

Notify BLM at 887-6544 prior to commencing P & A operations.

Notify NMOC D at 748-1283 prior to commencing P & A operations.

18. I hereby certify that the foregoing is true and correct

SIGNED

Dennis K. ...

TITLE

Prod. Supt.

DATE

7/17/89

(This space for Federal or State office use)

APPROVED BY

Shannon J. Shaw

FOR:

TITLE

MINERAL RESOURCES

DATE

8-1-89

Subject to
Like Approval
by State

*See Instructions on Reverse Side