September 7, 1962

Ray Smith P. O. Box 953 Midland, Texas

> He: Kenwood Federal "A" Unit-E, Well #1 Sec. 18-125-31E Eddy County, New Mexico

Dear Sir:

We are in receipt of your Form G-104, but note that the location reported theron shows the well to be located 2310' from the south line rather than 2310' from the north as shown or well survey plat.

We are returning Form U-104 in order that it be corrected if in error, if the well is actually located 2310° from the south line it will be necessary to file three (3) new copies of Form C-128 (well location plat.) We note the name of operator on your Form C-104 & C-110 does not agree with original file, please file Form C-110 showing change in operator.

Very truly yours,

OIL CONSERVATION CUMMISSION

B. L. Armstrong Supervisor, District #2

MLA/W