

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

NOV 28 1979

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> P&A		7. UNIT AGREEMENT NAME O. C. C.	
2. NAME OF OPERATOR Fullerton oil Co. Southland Royalty Company		8. FARM OR ACREAGE OFFICE Little	
3. ADDRESS OF OPERATOR 1100 Wall Towers West, Midland, Tx. 79701		9. WELL NO. 1-A	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit Letter A, 660 FNL, 660 FEL, Sec. 28 T-18S, R-31E		10. FIELD AND POOL, OR WILDCAT Shugart	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3633 GR	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 28 T-18S R-31E	
		12. COUNTY OR PARISH Eddy	
		13. STATE N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

REPAIRING WELL

☐
☐
☐
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) Re-enter & Re-plug ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-30-79 Rig up cleanout to 65'

11-1-79 Ran 2 joints 8 5/8" pipe & worked inside 10 3/4" casing
Dump 6 yds Redi-Mix behind 8 5/8 csg

11-2-79 Cmt thru 8 5/8" csg w/100 sx class "C" neat. Got good returns
outside of 8 5/8

11-3-79 Tag cmt @ 25' Drill solid cmt to 71' Drill to 305'
Drill on wood & metal to 410'

11-4-79 Drill to 418

11-5-79 thru 11-7-79 Ran Mill & Globe basket. Cleanout wood & metal
to 1018'

11-6-79 thru 11-14-79 Attempting to re-enter 7" csg stub. Encountered
wtr flow @ 1060'

11-15-79 Worked into 7" csg Ran Mill to 3475' displace hole w/10# mud

11-16-79 Spot 40sx plug from 3475 - 3275. Spot 55 sx plug from 2451 - 2121'
Spot 150 sx plug from 1121 - 863 Tag plug @ 863' Spot 125 sx plug
from 801-500'. Spot 25 sx plug from 120' - surface. Clean-up
location & install dry hole marker

18. I hereby certify that the foregoing is true and correct

SIGNED

C. Hamer Can

TITLE

District Engineer

DATE

Nov. 26, 1979

(This space for Federal or State office use)

APPROVED BY

(Orig. Sgd.) GEORGE H. STEWART

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: