

Form 3160-5
(July 1989)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on reverse
side)

BLM Roswell District
Modified Form No.
NM060-3160-4

5. LEASE DESIGNATION AND SERIAL NO.
LC-029287-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

SOUTHLAND ROYALTY COMPANY

3. ADDRESS OF OPERATOR

P.O. Box 51810, Midland, TX 79710-1810

3a. AREA CODE & PHONE NO.

915-688-6906

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

M, 330' FSL & 990' FWL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

SHUGART "A"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

SHUGART (Y-7R-QN-GB)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

29, T-18-S, R-31-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

NOT AVAILABLE

12. COUNTY OR PARISH

EDDY

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐

PULL OR ALTER CASING

☐

FRACTURE TREAT

☐

MULTIPLE COMPLETE

☐

SHOOT OR ACIDIZE

☐

ABANDON*

☐

REPAIR WELL

☐

CHANGE PLANS

☐

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐

REPAIRING WELL

☐

FRACTURE TREATMENT

☐

ALTERING CASING

☐

SHOOTING OR ACIDIZING

☒

ABANDONMENT*

☐

(Other) ADDED PERFS, ACID., & FRAC'D.

☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

ADDED YATES PERFS, ACIDIZED AND FRACTURE STIMULATED.

10-31-91 TOH W/RODS & TBG.

11-01-91 RAN GR/CCL LOG 3600'-2000'. PERF'D YATES 2594'-2620', 2SPF, 28 HOLES.

11-02-91 THRU 11-04-91 BROKE DOWN PERFS W/110 GALS SP-358, 330 GALS 2% KCL, FOLLOWED W/1000 GALLONS 7-1/2% NEFE HCL PLUS 56 BS. FRAC'D YATES W/17000 GALLONS 40# BORATE X-LINKED GEL & 54, 000# 12/20 BRADY SAND.

11-05-91 THRU 11-20-91 WASHED SAND. SWEDGE CASING. RIH W/ 2-3/8" PRODUCTION TUBING. RIH W/2" X 1-1/2" X 15' RHBC PUMP. TURN WELL TO PRODUCTION.

18. I hereby certify that the foregoing is true and correct

SIGNED

Wanda L. King

TITLE

PRODUCTION ASST.

DATE

12-30-91

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side