

SHUGART "A" NO. 5

QUEENS:

Perforations: 3174-3184';
3196-3206'; 3212-3222'
3 J.S.P.F.

Treatment: 500 gallons 15% NE acid.
Frac w/32,000 gallons gelled brine
and 29,500# 20/40 sand and 14,000#
10/20 sand

PENROSE:

Perforations: 3418-3428';
3478-3484'
2 J.S.P.F.

Treatment: 1000 gallons 15% NE acid.
Frac w/31,000 gallons gelled brine
and 30,000# 20/40 sand and 14,000#
10/20 sand

GRAYBURG:

Perforations: 3748-3758';
3774-3784'
2 J.S.P.F.

Treatment: 1,000 gallons 15% NE acid.
Frac w/21,000 gallons gelled brine
and 23,500# 20/40 sand and 6,000#
10/20 sand