Form	9-331
(May	1963)

NM COPERIST ASSISTED IN DFP

RS-CORY	_/\z	Έ
Other justruction.	- 3	r
aras Aspara)		

424. CST

	GEOLOGICAL SURVEY	AND DOCIU	LC-029387 (b)
	SUNDRY NOTICES AND REPORTS (Do not use this form for proposals to drill or to deepen or plus use "APPLICATION FOR PERMIT—" for the	ON WELLS back to a different reservoir. proposals. RECEIVED	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
ı.	OIL X CAS WELL OTHER	945D OF 1003	7. UNIT AGREEMENT NAME
2.	NAME OF OPERATOR	MHK S 3 1303	8. FARM OR LEASE NAME
	Southland Royalty Company		Shugart "C"
3.		O. C. D.	9. WELL NO.
	21 Desta Drive, Midland, Texas 79701 🖔	ARTESIA, OFFICE	1
4.	LOCATION OF WELL (Report location clearly and in accordance with an See also space 17 below.) At surface		10. FIELD AND POOL, OR WILDCAT Shugart (Y,SR,Q,G)
	330' FS & EL, Sec. 30, T-18-S, R-31-E		11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA
		DEC 26 '90	Sec. 30, t-18-S, R-31-I
14	PERMIT NO. 15. ELEVATIONS (Show whether		12. COUNTY OR PARISH 13. STATE
	Unknown	O. C. D.	Fddy N.M.
16.		Nature of Notice, Report, or C	· ·
	NOTICE OF INTENTION TO:	SUBSEQ	UENT REPORT OF:
	TEST WATER SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
	FRACTURE TREAT MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
	SHOOT OR ACIDIZE ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT* XX
	REPAIR WELL CHANGE PLANS	(Other)	
	(Other)	Completion or Recomp	of multiple completion on Well letion Report and Log form.)

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *
 - Set CIBP @ 3410'. Spot 50 sx Cl "C" from 3410-2900'. Pull tbg to 2900'. 1. MIRUPU.
 - Displ hole w/mud.
 - Tag cmt plug @ 3090'. Perf 2 sqz holes @ 2090'. Set cmt ret @ 1960'. GIH w/tbq & set in retainer.
 - Pmp 100 sx C1 "H" cmt.
 - Perf 2 sqz holes @ 760'. Circ out Bradenhead.
 - Pmp 200 sx cmt. Circ cmt. Cut off wellhead.
 - Weld on plate. RDPU. Install dry hole marker. Clean location.



MAR 3 0 1983

OHL & GAS MINERALS MGMT. SERVICE ROSWELL, NEW MEXICO

SIGNED SIGNED	TITLE District Operations Engineer	DATE _	3/24/83
(This space for Federal or State office use)	1.7		1.0/0.
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE TERMINATION OF THE TOTAL	DATE _	12/19/90
CONDITIONS OF ATTROVAL, IF ANY		٠	1 1 - 1 2

Approved as to plugging of the well bore. Liability under bond is retained until surface restoration is completed.

*See Instructions on Reverse Side

Port FD-2 4-8-83 P+A